**≎**EPA

Form Approved OMB No. 2040-0003

								Ul	NITEI	D STA	ΓES ENV W		IENTAL n, D.C. 2		ECTIO	N AGE	NCY													
	NPDES Compliance Inspection Report																													
Section A: National Data System Coding																														
Transaction Code											Ins 18	Inspec. Type Inspector Fac. Type 19 S 20 1																		
Remarks   7   0   -   0   0   3   4   1													Ī																	
	Inspection Work Days Facility Evaluat							tion I	Rating BI						QA						Reserved									
	67	specii	on w	VOFK I	Jays 69	)			га	7(	1		Catting		71	N	72	QA N	73			74	75		Reser	vea				80
														Sec	ction	B: Fa	cility	Data												
inclu	Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) El Dorado Water-South Plant													Entry Time/Date 8:54 /5/12/2009							Permit Effective Date 10/1/2008									
325	225 Quail Crossing El Dorado, AR													Exit Time/Date 15:51 /5/12/2009							Permit Expiration Date 9/30/2013									
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)  Harold Baker, Treatment Superintendent/870-862-6451  Other Facility Data																													
Larr El D P.O.	Name, Address of Responsible Official/Title/Phone and Fax Number Larry Waldrop, General Manager, 870-862-6451 El Dorado Water-South Plant P.O. Box 1587 El Dorado, AR 71731																Contacted Yes ✓ No □													
	Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																													
S	Per	Permit					I	N Flow Measureme							N	Op	erations & Maintenance					N	N Sampling							
N	Rec	Records/Reports				N	N Self-Monitoring					Program			Slu	dge H	dge Handling/Disposal					N	N Pollution Prevention							
N	<b>Facility Site Review</b>					N	1	Com	plianc	e Sche	dules			N	Pre	etreatment					N	N Multimedia								
N	Effluent/Receiving Waters					N			ratory			1					rm Water						Other:							
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)  This recon inspection was performed in conjunction with Patricia Willis, U.S. EPA Region 6. For complete inspection details, see EPA inspection report dated 5/12/009.																														
Name(s) and Signature(s) of Inspector(s)												/Telep									Date									
John W. Lamb								340	0 Wes	st. Hil	llsboro	, El E	nvironmental Quality orado, AR 71730 2-3509							28 May 2009										
Signature of Reviewer									Age	ency/0	Office	e/Phon	e and	Fax Numbers							Date									