

# ADEQ

ARKANSAS  
Department of Environmental Quality

August 9, 2011

Mr. Larry Waldrop  
El Dorado Water-South Plant  
P.O. Box 1587  
El Dorado, AR 71731

RE: Inspection/Complaint Investigation

AFIN: 70-00341


NPDES Permit No.: AR0033723

Dear Mr. Larry Waldrop:

On 7/26/2011, I performed an inspection of the El Dorado Water-South Plant facility in response to a complaint which alleged that the South Plant was emitting very obnoxious odors to residences on Southfield Road. This inspection was performed in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. The inspection revealed that there are no plant operational issues.

If I can be of any assistance, please contact me at 870-862-0680.

Sincerely,



John W. Lamb  
District 8 Field Inspector  
Water Division

cc: Water Division Enforcement Branch  
Water Division Permits Branch



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

## NPDES Compliance Inspection Report

Form Approved  
OMB No. 2040-0003

### Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type
1 <b>N</b> 2 <b>5</b> 3 <b>A R 0 0 3 3 7 2 3</b> 11 12 <b>1 1 0 7 2 6</b> 17 18 <b>R</b> 19 <b>S</b> 20 <b>1</b>	Remarks				
Inspection Work Days		Facility Evaluation Rating		BI QA -----Reserved-----	
67		69	70 <b>N</b>	71 <b>N</b> 72 <b>N</b> 73	74 75

### Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> ) <b>El Dorado Water-South Plant</b> <b>Quail Run Road</b> <b>El Dorado, AR</b>	Entry Time/Date <b>13:05 /7/26/2011</b>	Permit Effective Date <b>10/1/2008</b>
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) <b>John Peppers/Pretreatment Coordinator</b>	Other Facility Data <b>PDS Inspection # 060369</b>	
Name, Address of Responsible Official/Title/Phone and Fax Number <b>Larry Waldrop, 870-862-6451</b> <b>El Dorado Water-South Plant</b> <b>P.O. Box 1587</b> <b>El Dorado, AR 71731</b>	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

### Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	S	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
S	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water		Other:

### Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

**This inspection was performed in response to a complaint which alleged that very obnoxious odors were being emitted from the sewer system. On the date of the inspection, no operational errors were noted. The facility was cleaning grease out manholes near the area using the City's vacuum truck. The grease was being dewatered on the drying bed.**

Name(s) and Signature(s) of Inspector(s)  John W. Lamb	Agency/Office/Telephone/Fax Arkansas Department of Environmental Quality 3400 West. Hillsboro, El Dorado, AR 71730 870-862-0680/ Fax 870-862-3509	Date <b>08/02/2011</b>
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date