AFIN: 47-00956

Permit #: AR0021580

€EPA									Form Approved OMB No. 2040-0003	
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY										
Washington, D.C. 20460 NPDES Compliance Inspection Report										
Section A: National Data System Coding										
Transaction Code NPDES Yr/Mo/Day Inspector Fac. Type										
1 N 2 5 3 A R 0 0 2 1 5 8 0 11 12 1 2 0 3 2 7 17 18 H 19 S 20 1 Remarks										
4 7 - 0 0 9 5 6 M I S S I S I P P I C									C O U N T Y	
									Reserved	
Section B: Facility Data										
incl	ne and Location of Facility Inspected ade POTW name and NPDES permit of Osceola WWTP			charging to POTV	V, also	7, also Entry Time/Date 09:50 / April 19, 2012			Permit Effective Date February 01, 2011	
Osc	st side of CR 471, south of Hwy 14(eola, AR sissippi County					Exit Time/Date 11:00 / April 19, 2012		Permit Expiration Date January 31, 2016		
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data										
James Carlock / Water and Wastewater Treatment Superintendent / 870-563-2628									5.679585	
	Allred / Director of Public Works /		•		_				0.03858	
Name, Address of Responsible Official/Title/Phone and Fax Number James Carlock / Water and Wastewater Superintendent / 870-563-2628									S #065218	
City	of Osceola WWTP	perintendent / 0/0-	505-2028			Contacted				
	. Box 443 eola, AR 72370		Yes No			Yes No				
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)										
S	Permit	Flow Measureme			Operations & Maintenance		Ν	Sampling		
Ν	Records/Reports N Se		Self-Monitoring F	Self-Monitoring Program		Sludge Handling/Disposal		Ν	Pollution Prevention	
Ν	Facility Site Review N Compliance Sched		dules N		Pre	Pretreatment		Multimedia		
Ν	Effluent/Receiving Waters	luent/Receiving Waters N Laboratory			Ν	Storm Water		Ν	Other:	
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)										
This compliance assistance inspection was conducted at the request of Mr. James Carlock, City of Osceola Water and Wastewater Superintendent. At the time, Mr. Carlock was preparing a response to the last SSO inspection (PDS # 064946) and needed to discuss some of the plans for correcting the items noted in the previous report. Specifically, the plans to correct the open wet wells and ladder access to the screen areas at Country Club and Phillips pump stations were discussed with on-site representatives.										
No letter will be sent at this time.										
Nai	ne(s) and Signature(s) of Inspector(s		Agency/Office/Telephone/Fax					Date		
Middlehurz				AR Dept. of Environmental Quality-Jonesboro (870) 935-7221 ext. 15 / (870) 935-4715 (Fax)				April 19, 2012		
Mic	hael B. Greenway		/							
Sig	nature of Reviewer		Agency/Office/Phone and Fax Numbers				Date			