



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

NPDES Compliance Inspection Report

Form Approved
OMB No. 2040-0003

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type
1 N 2 5 3 A R 0 0 3 3 7 2 3 11 12 1 2 1 1 2 7 17 18 I 19 S 20 2					
Remarks					
7 0 - 0 0 3 4 1					
Inspection Work Days	Facility Evaluation Rating	BI	QA	-----Reserved-----	
67 69	70 N	71 N	72 N	73 	74 75 80

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) El Dorado Truck Wash 1909 Southwest Ave, El Dorado El Dorado Water , AR00033723	Entry Time/Date 10:28 /11/27/2012	Permit Effective Date 10/1/2008
	Exit Time/Date 12:03 /11/27/2012	Permit Expiration Date 9/30/2013
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Caleb Sindle/Owner, 870-862-0870	Other Facility Data PDS# 069403	
Name, Address of Responsible Official/Title/Phone and Fax Number Caleb Sindle, Owner, 870-862-0870 1909 Southwest Ave, El Dorado, AR	Contacted Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
U	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water		Other:

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This inspection was performed in conjunction with the Hazardous Waste Division and the El Dorado Water Utilities in regards to a complaint which the City and Hazardous Waste both received. Hazardous Waste and the City were both the lead on this inspection. See attached Hazardous Waste Report Summary.

NO LETTER SENT FROM WATER DIVISION

Name(s) and Signature(s) of Inspector(s) John W. Lamb	Agency/Office/Telephone/Fax Arkansas Department of Environmental Quality 3400 West. Hillsboro, El Dorado, AR 71730 870-862-0680/ Fax 870-862-3509	Date 20 December 2012
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

ACTION TAKEN: On November 27, 2012, ADEQ Water Inspector John Lamb and I, along with John Peppers and Harold Baker from El Dorado Water, conducted a complaint investigation at Sindle Trucking located at 1909 Southwest Avenue in El Dorado, Arkansas. The complainant alleges that hazardous waste is being washed down the truck wash and that he had seen methanol and gas oil washed off trucks. The complainant was also told that sulfuric acid had been washed down the truck drain.

When we arrived on-site, we met with Mr. Caleb Sindle, owner of Sindle Trucking. Mr. Sindle stated that the complainant was a former truck driver for the company but had recently been let go. Mr. Sindle also stated that the company only washes the outside of the trucks that come in and has never washed the inside of tankers. He said that he doesn't have the equipment or capability to wash the inside of the tankers, and if the inside of one does need to be cleaned it is sent to Louisiana. He also stated that he didn't have any hazardous waste stored at the facility.

During the walk through of the property, no hazardous waste was found on-site but there were some used oil concerns. There was a tote of used oil in the maintenance shop that was not labeled as well as a 55-gallon drum beside the tote. There were three (3) 55-gallon drums of used oil filters that did not have a label located outside of the maintenance shop as well as a used oil tank (approximately 1,000 gallons) that was not labeled. The soil around the used oil tank and used oil filter drums had been contaminated with oil. I instructed him to label all of his used oil containers properly and clean up the oil contaminated area. Mr. Sindle had paperwork showing that Safety Kleen picks up the used oil at the facility routinely.

There were also approximately 20 truck batteries sitting on the ground behind the maintenance shop. Mr. Sindle was instructed to move them to a protected area and store them correctly.

Mr. Sindle stated that he would immediately have the used oil containers labeled, the batteries stored properly, and the contaminated area cleaned up.

On December 3, 2012, I received photographs showing the contaminated area has been cleaned. Mr. Sindle stated that he has labels being printed and will have them within the next few days. Photographs also showed that the batteries have been stored properly.