

 <p style="text-align: center;">UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460</p> <h2 style="text-align: center;">NPDES Compliance Inspection Report</h2>	Form Approved OMB No. 2040-0003
--	------------------------------------

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type				
1 <input type="text" value="N"/> 2 <input type="text" value="5"/> 3 <input type="text" value="A"/> <input type="text" value="R"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="3"/> <input type="text" value="3"/> <input type="text" value="7"/> <input type="text" value="2"/> <input type="text" value="3"/> 11 <input type="text" value="1"/> 12 <input type="text" value="3"/> <input type="text" value="0"/> <input type="text" value="4"/> <input type="text" value="1"/> <input type="text" value="6"/> 17 <input type="text" value="R"/> 18 <input type="text" value="S"/> 19 <input type="text" value="S"/> 20 <input type="text" value="1"/>	Remarks								
Inspection Work Days		Facility Evaluation Rating		BI		QA		-----Reserved-----	
67 <input type="text" value=""/> <input type="text" value=""/> 69		70 <input type="text" value="N"/>		71 <input type="text" value="N"/>		72 <input type="text" value="N"/>		73 <input type="text" value=""/> 74 <input type="text" value=""/> 75 <input type="text" value=""/> 80	

Section B: Facility Data



Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) City of El Dorado-South Plant W. Cook Street El Dorado, AR	Entry Time/Date 8:59 /4/16/2013	Permit Effective Date 10/1/2008
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Joe Eaton, Distribution Superintendent/870-862-6451 John Peppers, Assistant Treatment Superintendent, 870-862-6451	Other Facility Data Major Municipal	
Name, Address of Responsible Official/Title/Phone and Fax Number Larry Waldrop, General Manager, 870-862-6451 City of El Dorado-South Plant P.O. Box 1587 El Dorado, AR 71731	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

Section C: Areas Evaluated During Inspection
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	S	Other: SSO

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This inspection was performed in response to a complaint, which alleged raw sewage was discharging from cleanouts on W. Cook Street near South West Avenue. The inspection revealed that a raw sewage discharge had occurred at the location, but this discharge was from a stoppage of private service line and not from or caused by the City's line. The private service line had already been repaired by a local plumber.

Name(s) and Signature(s) of Inspector(s)  John W. Lamb	Agency/Office/Telephone/Fax Arkansas Department of Environmental Quality 3400 West. Hillsboro, El Dorado, AR 71730 870-862-0680/ Fax 870-862-3509	Date 18 April 2013
Signature of Reviewer Kerri McCabe, Inspector Supervisor 	Agency/Office/Phone and Fax Numbers Arkansas Department of Environmental Quality 5301 Northshore Drive, N. Little Rock, AR 72118 501-682-0642 fax 501-682-0880	Date April 18, 2013