



ARKANSAS  
Department of Environmental Quality

# WATER DIVISION INSPECTION REPORT

AFIN: 47-00956	PERMIT #: AR0021580	
COUNTY: 47 Mississippi	PDS #: 076941	MEDIA: WN
GPS LOCATION: LAT: 35.679585 LONG: -90.03858		
<input type="checkbox"/> Outfall / <input type="checkbox"/> General Area / <input checked="" type="checkbox"/> Entrance / <input type="checkbox"/> Sample Point		

FACILITY INFORMATION	INSPECTION INFORMATION
NAME: <b>City of Osceola WWTP</b>	DATE(S): <b>3/13/2014</b>
LOCATION: <b>West Side of CR 471, South of Hwy 140</b>	ENTRY TIME: <b>11:05</b>
	EXIT TIME: <b>14:00</b>
CITY: <b>Osceola, AR</b>	INSPECTION TYPE: <b>SSO/Collection System</b>
RESPONSIBLE OFFICIAL	INSPECTOR ID#: <b>86009 S - State</b>
CONTACTED DURING INSPECTION: <b>Yes</b>	FACILITY TYPE: <b>1 - Municipal</b>
NAME: <b>James Carlock</b>	PERMIT EFFECTIVE DATE: <b>2/1/2011</b>
TITLE: <b>Water and Wastewater Superintendent</b>	PERMIT EXPIRATION DATE: <b>1/31/2016</b>
COMPANY: <b>City of Osceola</b>	FACILITY EVALUATION RATING: <b>N</b>
MAILING P.O. Box 443	FAYETTEVILLE SHALE RELATED: <b>N</b>
ADDRESS:	FAYETTEVILLE SHALE VIOLATIONS: <b>N</b>
CITY, STATE, ZIP: <b>Osceola, AR 72370</b>	INSPECTION PARTICIPANTS
PHONE & EXT: <b>870-563-2628</b>	NAME/TITLE/PHONE/FAX/EMAIL/ETC.:
FAX: <b>N/A</b>	<b>James Carlock / Water and Wastewater Superintendent / 870-563-2628</b>
EMAIL: <b>N/A</b>	
OTHER: <b>N/A</b>	

AREA EVALUATIONS					
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)					
<b>S</b>	PERMIT	<b>**</b>	FLOW MEASUREMENT	<b>**</b>	STORMWATER
<b>S</b>	RECORDS/REPORTS	<b>**</b>	LABORATORY	<b>S</b>	FACILITY SITE REVIEW
<b>S</b>	OPERATION & MAINTENANCE	<b>**</b>	EFFLUENT/RECEIVING WATER	<b>**</b>	SELF-MONITORING PROGRAM
<b>**</b>	SAMPLING	<b>**</b>	SLUDGE HANDLING/DISPOSAL	<b>**</b>	PRETREATMENT
<b>S</b>	OTHER: <b>SSO</b>				

**SUMMARY OF FINDINGS**

This Sanitary Sewer Overflow inspection was performed during the course of a routine compliance inspection of the Osceola wastewater treatment plant. At the time of inspection, it appeared that the facility was operating in compliance with the conditions of the Permit. The items noted in the previous inspection have been corrected and no additional action is necessary at this time.

**GENERAL COMMENTS**

Refer to the March 13, 2014 Compliance Evaluation Inspection for additional information.

INSPECTOR'S SIGNATURE: <b>Michael Greenway</b>	DATE: <b>3/21/2014</b>
SUPERVISOR'S SIGNATURE: <b>Jason Bolenbaugh</b>	DATE: <b>3/28/2014</b>

**Water Division Photographic Evidence Sheet**

Location:	<b>City of Osceola WWTP, Country Club Pump Station</b>				
Photographer:	<b>Michael Greenway</b>	Date:	<b>3/13/2014</b>	Time:	<b>11:46</b>
Witness:	<b>None</b>	Photo #:	<b>1</b>		
Description:	<b>View of improvements made to the Country Club Lift Station.</b>				

