

 <b>A R K A N S A S</b> Department of Environmental Quality		<b>WATER DIVISION INSPECTION REPORT</b>				
		AFIN: <b>70-00341</b>		PERMIT #: <b>AR0033723</b>		DATE: <b>6/12/2014</b>
		COUNTY: <b>70 Union</b>		PDS #: <b>078538</b>		MEDIA: <b>WN</b>
		GPS LAT: <b>33.199013</b> LONG: <b>-92.686837</b> LOCATION: <b>General Area</b>				
<b>FACILITY INFORMATION</b>			<b>INSPECTION INFORMATION</b>			
NAME: <b>Kehl Solutions</b> LOCATION: <b>1568 Haynesville Hwy</b> CITY: <b>EI Dorado, AR 71730</b>			FACILITY TYPE: <b>2 - Industrial</b>	INSPECTOR ID#: <b>101531 S - State</b>		
			FACILITY EVALUATION RATING: <b>4 - Satisfactory</b>		INSPECTION TYPE: <b>Industrial User</b>	
			DATE(S): <b>6/12/2014</b>	ENTRY TIME: <b>14:05</b>	EXIT TIME: <b>15:01</b>	PERMIT EFFECTIVE DATE:  PERMIT EXPIRATION DATE:
<b>RESPONSIBLE OFFICIAL</b>						
NAME / TITLE: <b>Chris Lee / Owner</b> COMPANY: <b>Kehl Solutions</b> MAILING ADDRESS: <b>1568 Haynesville Hwy</b> CITY, STATE, ZIP: <b>EI Dorado AR 71730</b> PHONE & EXT: / FAX: <b>870-639-3769 /</b> EMAIL:			FAYETTEVILLE SHALE RELATED: <b>N</b> FAYETTEVILLE SHALE VIOLATIONS: <b>N</b>			
CONTACTED DURING INSPECTION: <b>Yes</b>			<b>INSPECTION PARTICIPANTS</b>			
			NAME/TITLE/PHONE/FAX/EMAIL/ETC.: <b>Harold Baker/Treatment Superintendent/870-862-6451</b> <b>Jay Culpepper/Pretreatment/870-862-6451</b> <b>Kerri McCabe/ADEQ Inspector Supervisor</b> <b>Brent Walker/ADEQ District 3 Water Inspector</b>			
<b>AREA EVALUATIONS</b>						
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)						
<b>S</b>	PERMIT	<b>N</b>	FLOW MEASUREMENT	<b>N</b>	STORMWATER	
<b>S</b>	RECORDS/REPORTS	<b>S</b>	LABORATORY	<b>M</b>	FACILITY SITE REVIEW	
<b>S</b>	OPERATION & MAINTENANCE	<b>N</b>	EFFLUENT/RECEIVING WATER	<b>S</b>	SELF-MONITORING PROGRAM	
<b>S</b>	SAMPLING	<b>N</b>	SLUDGE HANDLING/DISPOSAL	<b>S</b>	PRETREATMENT	
<b>**</b>	OTHER:					
<b>SUMMARY OF FINDINGS</b>						
No violations noted during the inspection.						
<b>GENERAL COMMENTS</b>						
Kehl Solutions was visited during the PCI because it was discussed that the facility may be a categorical IU that has not responded to EWU's survey. Kehl Solutions does some interior tank washing of crude oil, diesel and ethanol tanker trucks. This process wash water is contained in a 2,000 gallon oil and grease separator (see Photo 1). The oil/water mix is then pumped into a FCC Environmental tanker truck and disposed of. EWU will add Kehl Solutions to their categorical IUs, but list them as a "no discharge" facility.						
It was also discovered during the IU site visit that Kehl Solutions does not have an IGP permit. A reconnaissance inspection form will accompany this IU site visit form.						
INSPECTOR'S SIGNATURE:  <b>Michael D. Young</b>				DATE: <b>06/23/2014</b>		
SUPERVISOR'S SIGNATURE:  <b>Kerri McCabe</b>				DATE: <b>6/26/2014</b>		

PRETREATMENT COMPLIANCE INSPECTION

IU SITE VISIT FORM

Name of Industry: **Kehl Solutions**

POTW Name: **El Dorado Water Utility**

Industry Contacts: **Chris Lee 870-639-3769**

Date and Time of Visit: **06/12/2014 14:05**

Description of Manufacturing Process:  
**Truck and Tank Wash. Facility washes interior of Martin Transport tanks carrying crude oil, diesel and ethanol.**

**FCC Environmental collects all oily water mixture from holding tank and disposes offsite.**

Sources of Process Wastewater:  
**Trucks and tanks.**

Categorical Industry? **Not currently permitted**

Basis for Limits: **N/A**

Point of Application: **N/A**

Description of Pretreatment Equipment and Procedures:  
**Oil and Grease separator**

Spill Prevention and Solvent Management Procedures:  
**Spill kits; Absorbent pads/booms**

Sampling Location and Equipment:  
**N/A**

**POTW Pretreatment Program**

**Industrial Site Visit**

Name of Industry: Kehl Solutions \_\_\_\_\_

Industry Contacts: Chris Lee \_\_\_\_\_

Type of Industry: Truck/Tank wash \_\_\_\_\_

Date of Visit: 06/12/2014 \_\_\_\_\_

- |  |                    |                   |                               |
|--|--------------------|-------------------|-------------------------------|
| 1. Significant industrial user:                        | _____ Yes          | _____ No          | <b>X</b> _____ Not Determined |
| 2. Pretreatment equipment or procedures?               | <b>X</b> _____ Yes | _____ No          | _____ N/A                     |
| 3. Pretreatment equipment maintained and operational?  | <b>X</b> _____ Yes | _____ No          | _____ N/A                     |
| 4. Hazardous waste generated or stored?                | _____ Yes          | <b>X</b> _____ No | _____ N/A                     |
| 5. Proper solid waste disposal?                        | <b>X</b> _____ Yes | _____ No          | _____ N/A                     |
| 6. Solvent management/TTO control?                     | _____ Yes          | _____ No          | <b>X</b> _____ N/A            |
| 7. Suitable sampling location?                         | _____ Yes          | _____ No          | <b>X</b> _____ N/A            |
| 8. Appropriate self-monitoring procedures / equipment? | <b>X</b> _____ Yes | _____ No          | _____ N/A                     |
| 9. Adequate spill prevention?                          | <b>X</b> _____ Yes | _____ No          | _____ N/A                     |
| 10. Industry familiar with limits and requirements?    | _____ Yes          | <b>X</b> _____ No | _____ N/A                     |

Additional Comments: Facility is a categorical industrial user (IU) but is currently not discharging\_ to El Dorado Water Utility (EWU). EWU will add Kehl Solutions to their categorical IUs but list them as a "no discharge" user.

Visit Conducted By: Michael D. Young Date: 06-23-2014

**Water Division Photographic Evidence Sheet**

Location:	<b>Kehl Solutions</b>				
Photographer:	<b>Michael Young</b>	Date:	<b>06-12-2014</b>	Time:	<b>14:43</b>
Witness:	<b>Harold Baker; Jay Culpepper; Chris Lee; Kerri McCabe; Brent Walker</b>			Photo #:	<b>1</b>
Description:	<b>Oil and grease separator at Kehl Solutions.</b>				

