

 <b>A R K A N S A S</b> Department of Environmental Quality		<b>WATER DIVISION INSPECTION REPORT</b>				
		AFIN: <b>47-00956</b>		PERMIT #: <b>AR0021580</b>		DATE: <b>9/8/2014</b>
		COUNTY: <b>47 Mississippi</b>		PDS #: <b>080045</b>		MEDIA: <b>WN</b>
		GPS LAT: <b>35.679585</b> LONG: <b>-90.03858</b> LOCATION: <b>Entrance</b>				
<b>FACILITY INFORMATION</b>			<b>INSPECTION INFORMATION</b>			
NAME: <b>City of Osceola WWTP</b> LOCATION: <b>West side of CR 471, South of Hwy 140</b> CITY: <b>Osceola, AR</b>			FACILITY TYPE: <b>1 - Municipal</b>	INSPECTOR ID#: <b>86009 S - State</b>		
			FACILITY EVALUATION RATING: <b>***</b>	INSPECTION TYPE: <b>Reconnaissance</b>		
			DATE(S): <b>9/8/2014</b>	ENTRY TIME: <b>13:55</b>	EXIT TIME: <b>14:12</b>	PERMIT EFFECTIVE DATE: <b>2/1/2011</b>  PERMIT EXPIRATION DATE: <b>1/31/2016</b>
<b>RESPONSIBLE OFFICIAL</b>						
NAME / TITLE: <b>Dickie Kennemore / Mayor</b> COMPANY: <b>City of Osceola</b> MAILING ADDRESS: <b>P.O. Box 443</b> CITY, STATE, ZIP: <b>Osceola AR 72730</b> PHONE & EXT. / FAX: <b>870-563-5102 /</b> EMAIL: <b>N/A</b>						
CONTACTED DURING INSPECTION: <b>No</b>						
<b>AREA EVALUATIONS</b>						
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)						
<b>S</b>	PERMIT	<b>**</b>	FLOW MEASUREMENT	<b>**</b>	STORMWATER	
<b>**</b>	RECORDS/REPORTS	<b>**</b>	LABORATORY	<b>**</b>	FACILITY SITE REVIEW	
<b>S</b>	OPERATION & MAINTENANCE	<b>**</b>	EFFLUENT/RECEIVING WATER	<b>**</b>	SELF-MONITORING PROGRAM	
<b>**</b>	SAMPLING	<b>**</b>	SLUDGE HANDLING/DISPOSAL	<b>**</b>	PRETREATMENT	
<b>**</b>	OTHER:					
<b>SUMMARY OF FINDINGS</b>						
There were no violations noted during this inspection.						
<b>GENERAL COMMENTS</b>						
An unrelated complaint was investigated nearby. The inspector performed a reconnaissance inspection while in the area.						
INSPECTOR'S SIGNATURE:  <b>Michael Greenway</b>				DATE: <b>9/19/2014</b>		
SUPERVISOR'S SIGNATURE:  <b>-Supervisor Name</b>				DATE: <b>9/26/2014</b>		

**Water Division Photographic Evidence Sheet**

Location:	<b>City of Osceola WWTP</b>		
Photographer:	<b>Michael Greenway</b>	Date:	<b>9/8/2014</b>
Time:	<b>14:01</b>	Witness:	<b>None</b>
Photo #:	<b>1</b>	Description:	<b>View of the facility and first lagoon cell.</b>



Photographer:	<b>Michael Greenway</b>	Date:	<b>9/8/2014</b>
Time:	<b>14:09</b>	Witness:	<b>None</b>
Photo #:	<b>2</b>	Description:	<b>View of the facility and the final lagoon cell in background.</b>

