



A R K A N S A S  
Department of Environmental Quality

## MEMORANDUM

TO: Richard Healey, Enforcement Branch, Water Division

Through: Kerri McCabe, Inspector Supervisor, Water Division

From: Steven L. Henderson, District 6 Inspector, Water Division

Date: July 7, 2015

Subject: City of Stuttgart WWTP (Arkansas Co)  
AFIN: 01-00214 NPDES Permit No.: AR0034380

On June 17, 2015, a Reconnaissance Inspection was conducted to determine the status of the levee breach on the west-side of the EQ basin located at the City's wastewater treatment facility. At the time of inspection, the discharge of wastewater from the EQ Basin had been stopped. The levee appeared to be approximately eighty-five percent complete. According to Tommy Lawson, Manager, Stuttgart Municipal Waterworks, a little more dirt and compacting of the levee should finish the project.

<h1 style="margin:0;">ADEQ</h1> <p style="margin:0; font-weight: normal;">A R K A N S A S Department of Environmental Quality</p>	<b>WATER DIVISION INSPECTION REPORT</b>				
	AFIN: 01-00214	PERMIT #: AR0034380	DATE: 6/17/2015		
	COUNTY: 01 Arkansas	PDS #: 085067	MEDIA: WN		
	GPS LAT: 34.494038 LONG: -91.564306 LOCATION: General Area				
<b>FACILITY INFORMATION</b>		<b>INSPECTION INFORMATION</b>			
NAME: <b>City of Stuttgart WWTP</b> LOCATION: <b>10<sup>th</sup> Street Extension</b> CITY: <b>Stuttgart, AR</b>		FACILITY TYPE: <b>1 - Municipal</b> INSPECTOR ID#: <b>26075 S - State</b> FACILITY EVALUATION RATING: <b>3 - Satisfactory</b> INSPECTION TYPE: <b>Reconnaissance</b>			
<b>RESPONSIBLE OFFICIAL</b>		DATE(S): <b>6/17/2015</b> ENTRY TIME: <b>12:30</b> EXIT TIME: <b>13:30</b> PERMIT EFFECTIVE DATE: <b>2/1/2015</b> PERMIT EXPIRATION DATE: <b>1/31/2020</b>			
NAME / TITLE: <b>Tommy Lawson, / Manager</b> COMPANY: <b>City of Stuttgart</b> MAILING ADDRESS: <b>P.O. Box 130</b> CITY, STATE, ZIP: <b>Stuttgart, AR 72160</b> PHONE & EXT. / FAX: <b>870-674- 7115 /</b> EMAIL:		FAYETTEVILLE SHALE RELATED: <b>N</b> FAYETTEVILLE SHALE VIOLATIONS: <b>N</b>			
CONTACTED DURING INSPECTION: <b>Yes</b>		<b>INSPECTION PARTICIPANTS</b>			
		NAME/TITLE/PHONE/FAX/EMAIL/ETC.:			
<b>AREA EVALUATIONS</b>					
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)					
<b>S</b>	PERMIT	<b>N</b>	FLOW MEASUREMENT	<b>N</b>	STORMWATER
<b>N</b>	RECORDS/REPORTS	<b>N</b>	LABORATORY	<b>S</b>	FACILITY SITE REVIEW
<b>N</b>	OPERATION & MAINTENANCE	<b>N</b>	EFFLUENT/RECEIVING WATER	<b>N</b>	SELF-MONITORING PROGRAM
<b>N</b>	SAMPLING	<b>N</b>	SLUDGE HANDLING/DISPOSAL	<b>N</b>	PRETREATMENT
<b>S</b>	OTHER: <b>EQ Basin</b>				
<b>SUMMARY OF FINDINGS</b>					
See memo cover page for comments.					
<b>GENERAL COMMENTS</b>					
INSPECTOR'S SIGNATURE: <i>Steven L. Henderson</i> Steven L. Henderson					DATE: 6/22/2015
SUPERVISOR'S SIGNATURE: <i>Kerri McCabe</i> Kerri McCabe					DATE: 7/7/2015

**Water Division Photographic Evidence Sheet**

Location:	<b>City of Stuttgart WWTP-EQ Basin</b>		
Photographer:	<b>Steven L. Henderson</b>	Date:	<b>6/17/2015</b>
Time:	<b>12:41</b>	Witness:	<b>N/A</b>
Photo #:	<b>1</b>	Description:	<b>Inside of EQ basin levee.</b>



Photographer:	<b>Steven L. Henderson</b>	Date:	<b>6/17/2015</b>
Time:	<b>12:41</b>	Witness:	<b>N/A</b>
Photo #:	<b>2</b>	Description:	<b>Outside of EQ basin levee.</b>





**Water Division Photographic Evidence Sheet**

Location:	<b>City of Stuttgart WWTP-EQ Basin</b>		
Photographer:	<b>Steven L. Henderson</b>	Date:	<b>6/17/2015</b>
Time:	<b>12:42</b>	Witness:	<b>N/A</b>
Photo #:	<b>3</b>	Description:	<b>Top of EQ basin levee.</b>



Photographer:	<b>Steven L. Henderson</b>	Date:	<b>6/17/2015</b>
Time:	<b>12:42</b>	Witness:	<b>N/A</b>
Photo #:	<b>4</b>	Description:	<b>Top of EQ basin levee.</b>

