

 A R K A N S A S Department of Environmental Quality		WATER DIVISION INSPECTION REPORT				
		AFIN: 18-00110		PERMIT #: AR0021971		DATE: 4/21/2015
		COUNTY: 18 Crittenden		PDS #: 085173		MEDIA: WN
		GPS LAT: 35.19036 LONG: -90.22844 LOCATION: Entrance				
FACILITY INFORMATION			INSPECTION INFORMATION			
NAME: City of Marion STP LOCATION: 5054 Hardin Rd. CITY: Marion			FACILITY TYPE: 1 - Municipal	INSPECTOR ID#: 52138 S - State		
			FACILITY EVALUATION RATING: N	INSPECTION TYPE: Reconnaissance		
			DATE(S): 4/21/2015	ENTRY TIME: 13:55	EXIT TIME: 14:30	PERMIT EFFECTIVE DATE: 12/1/2013 PERMIT EXPIRATION DATE: 6/30/2017
RESPONSIBLE OFFICIAL			INSPECTION PARTICIPANTS			
NAME / TITLE: Frank Fogleman / Mayor COMPANY: City of Marion MAILING ADDRESS: 14 Military Rd. CITY, STATE, ZIP: Marion AR 72364 PHONE & EXT. / FAX: 870-739-5410 / EMAIL:						
CONTACTED DURING INSPECTION: No			INSPECTION PARTICIPANTS			
AREA EVALUATIONS						
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)						
S	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER	
N	RECORDS/REPORTS	N	LABORATORY	M	FACILITY SITE REVIEW	
M	OPERATION & MAINTENANCE	S	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM	
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT	
N	OTHER:					
SUMMARY OF FINDINGS						
<p>This reconnaissance inspection was performed to determine if the facility was still bypassing the rock reed filters and discharging out of an unpermitted discharge.</p> <p>At the time of the inspection the unpermitted discharges had ceased and it appeared flow through the facility was per design. Two of the rock reed filters were disabled.</p> <p>Construction work was underway for the new chlorine contact chamber and pumping station.</p> <p>No letter will be sent.</p>						
GENERAL COMMENTS						
Water Division Branch Manager - Jason Bolenbaugh and Inspector - Chris Naus were also present.						
INSPECTOR'S SIGNATURE: 				DATE: 7/13/2015		
SUPERVISOR'S SIGNATURE: 				DATE: 7/13/2015		

Water Division Photographic Evidence Sheet

Location:	City of Marion STP			
Photographer:	Brent Walker	Date:	4/21/2015	
Witness:	Jason Bolenbaugh & Chris Naus		Time:	1424
Description:	Previous unpermitted discharge locations.		Photo #:	1



Photographer:	Brent Walker	Date:	4/21/2015	Time:	1425
Witness:	Jason Bolenbaugh & Chris Naus			Photo #:	2
Description:	Discharge from Outfall 001				

