Inspection Report: Hiram Walker Pernod Richard , AFIN: 66-01652, Permit #: AR0021750

	OFFICE OF WATER INSPECTION REPORT							
AUEU			AFIN: 66-01652 PERMIT #: AR00		21750		DATE: 6/7/2017	
ARKANSAS		COUNTY: 66 Sebas		stian	PDS #: 097830			MEDIA: WN
	partment of Environmental Quality	37 LONG: -94.386313 LOCATION: Entrance						
	FACILITY INFORMAT	ION		INSPECTION INFORMATION				
Hiram Walker Pernod Richard			FACILITY TYPE: 2 - Industrial	inspector id#: 71330 S - State				
740 CITY:	01 Highway 45			FACILITY EVALUATION RATIN 3 - Satisfactory	'	Industrial User		
-	rt Smith			· ,	O:00	EXIT TIME: 10:40		FECTIVE DATE:
	RESPONSIBLE OFFIC	CIAL		0/1/2017	0.00	10.40	2/1/20 PERMIT EXE	15 PIRATION DATE:
	rl Geffken / City Administrator						1/31/2	
COME	PANY:			FAYETTEVILLE	SHAL	E RELATE	D: N	
	rt Smith, City of			FAYETTEVILLE SHALE VIOLATIONS: N				
	D. Box 1908			INSPECTION PARTICIPANTS				
. ,	STATE, ZIP:			NAME/TITLE/PHONE/FAX/EMAIL/ETC: John Hancock/Supervisor Environmental				
	rt Smith AR 72902			Monitoring/479.784.2335/jhancock@fortsmithar.gov				
	9-494-3908 /			Don Clover/Program Manager Environmental				
EMAII				Quality/479.784.2337/dclover@fortsmithar.gov				
	cavoy@fortsmithar.gov	NI -		Chris Cooper/Pretreatment				
CC	INTACTED DURING INSPECTION:	NO		Coordinator/479.784.1019/ccooper@fortsmithar.gov				
				Kerri McCabe/ADEQ Inspector				
				Supervisor/501.682.0642/mccabe@adeq.state.ar.us				
				Scott Horton/Plant Operations Manager/479.288.0225 Randy Williams/Operator				
			Raildy Williams/Operator					
AREA EVALUATIONS (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)								
**	PERMIT	**	FLOW MEASUR		**	STORMW	/ATER	
**	RECORDS/REPORTS	**	LABORATORY		**	FACILITY	SITE RE	VIEW
**	OPERATION & MAINTENANCE	**	EFFLUENT/REG	**	* SELF-MONITORING PROGRAM			
**	SAMPLING	** SLUDGE HANDLING/DISPOSAL			S	S PRETREATMENT		
**	OTHER:							
SUMMARY OF FINDINGS								
No	No violations were noted relative to the City of Fort Smith's Pretreatment Program during inspection.							

Inspection Report: Hiram Walker Pernod Richard, AFIN: 66-01652, Permit #: AR0021750

GENERAL COMMENTS

I inspected this facility with the above-referenced inspection participants on June 7, 2017. Inspection consisted of a pretreatment plant assessment and discussion designed to ascertain the IU's familiarity with the City's pretreatment program. The facility was well-maintained and effluent was clear at the outfall. Treatment consisted of three equalization tanks, two bio-towers (pH adjustment and nutrients added as needed), two clarifiers, and a sludge aeration tank. The facility also maintains three onsite lift stations, which collect the process water and deliver it to the pretreatment plant. The Operator informed that the lining on one of the equalization tanks had recently failed and a temporary liner repair was completed. A new liner is projected for install, and Mr. Horton stated that he anticipated that this liner would be installed in early July 2017. At the time of the inspection, the temporary liner patch was holding and the tank was not leaking.

During inspection, it was noted that the facility is conducting industrial activities without coverage under the Industrial Stormwater General Permit (IGP; ARR000000) required under the National Pollutant Discharge Elimination System and the Arkansas Water and Air Pollution Control Act and administered by the Arkansas Department of Environmental Quality. A separate report will be submitted to the facility advising them of their requirement to obtain coverage under the IGP.

Facility representatives were well-versed in the City's pretreatment program requirements and in their obligations under the program. Nothing of concern related to the City of Fort Smith's pretreatment program was noted during inspection.

INSPECTOR'S SIGNATURE:

Dannielle Gray

DATE: 6/14/2017

SUPERVISOR'S SIGNATURE:

Kerri McCabe

DATE: 6/29/2017

Inspection Report: Hiram Walker Pernod Richard , AFIN: 66-01652, Permit #: AR0021750

POTW Pretreatment Program

Industrial Site Visit

Hiram Walker Pernod Richard USA

Scott Horton & Randy Williams

Name of Industry:

Industry Contacts:

Тур	oe of Industry: Distil	led and Blended Liquors; V	Vine and I	Distilled .	Alcoholic	Beverag	es	
<u>Dat</u>	e of Visit: June 7, 2017							
1.	Significant industrial (user?	X	Yes		No		NA
2.	Pretreatment equipme	nt or procedures?	X	Yes		No		NA
3.	Pretreatment equipme operational?	nt maintained and	<u> x</u>	Yes		No		NA
4.	Hazardous waste gene	erated or stored?		Yes	<u> x</u>	No		NA
5.	Proper solid waste dis	posal?	X	Yes		No		NA
6.	Solvent management/	TTO control?	X	Yes		No		NA
7.	Suitable sampling loca	ation?	X	Yes		No		NA
8.	Appropriate self-moni procedures/equipmen		<u> x</u>	Yes		No		NA
9.	Adequate spill preven	tion?	<u> </u>	Yes		No		NA
10.	Industry familiar with	limits and requirements?	X	Yes		No		NA
duri Stor Syst Env	ng inspection. The facil rmwater General Permit tem and the Arkansas W	ning of concern related to the ity is conducting industrial (IGP; ARR000000) required later and Air Pollution Contexparate report will be submoder.	activities under the rol Act an	without Nationand	coverage al Pollutai istered by	under that Int Discha Int the Arka	e Indust rge Elimi ansas De	rial ination epartment of
Visi	t Conducted By: Dann	ielle Gray						
Date	e of Report: June	14, 2017						

Inspection Report: Hiram Walker Pernod Richard , AFIN: 66-01652, Permit #: AR0021750

Office of Water Photographic Evidence Sheet								
Location: Hiram Walker Pernod Richard								
Photographer: Dannielle Gray Date: 6/7/2017 Time: 1014								
Witness: Kerri McCabe, John Hancock, Don Clover, Chris Cooper, Scott Horton, Randy Williams					1			
Description: Pretreatment plant overview								



Photographer: Dannielle Gray	Date:	6/7/2017	Time:	1018
Witness: Kerri McCabe, John Hancock, Don Randy Williams	Clover, Chris Coo	oper, Scott Horton,	Photo #:	2

Description: Aeration tank post bio-tower





Photographer: Dannielle Gray	Date: 6/7/2017	Time:	1020
Witness: Kerri McCabe, John Hancock, Don Cl	over, Chris Cooper, Scott Horton,	Photo #:	4

Description: Flowmeter






Figure 1. Google Earth image dated March 20, 2016 showing facility overview and pretreatment plant location.

