



ENVIRONMENTAL  
QUALITY

# OFFICE OF WATER QUALITY INSPECTION REPORT

AFIN: 28-00047	PERMIT #: AR0033766	DATE: 12/8/2021
COUNTY: 28 Greene	PDS #: 123342	MEDIA: WN
GPS LAT: 36.031471 LONG: -90.491622 LOCATION: Entrance		

### FACILITY INFORMATION

NAME:  
**Paragould Light, Water & Cable**

LOCATION:  
**401 Grant Lane**

CITY:  
**Paragould**

### INSPECTION INFORMATION

FACILITY TYPE: <b>1 - Municipal</b>	INSPECTOR ID#: <b>112347 S - State</b>		
FACILITY EVALUATION RATING: <b>N</b>	INSPECTION TYPE: <b>Industrial User</b>		
DATE(S): <b>12/8/2021</b>	ENTRY TIME: <b>13:46</b>	EXIT TIME: <b>14:20</b>	PERMIT EFFECTIVE DATE: <b>3/1/2021</b>
			PERMIT EXPIRATION DATE: <b>2/28/2026</b>

### RESPONSIBLE OFFICIAL

NAME: / TITLE  
**Darrell Phillips / General Manager & CEO**

COMPANY:  
**Paragould Light, Water & Cable**

MAILING ADDRESS:  
**P.O. Box 9**

CITY, STATE, ZIP:  
**Paragould AR 72451**

PHONE & EXT: / FAX:  
**/**

EMAIL:

FAYETTEVILLE SHALE RELATED: **N**

FAYETTEVILLE SHALE VIOLATIONS: **N**

### INSPECTION PARTICIPANTS

NAME/TITLE/PHONE/FAX/EMAIL/ETC.:

**Lisa Ellington, PhD/ Environmental Services Manager**  
**David Romine, P.E./ WWTP Operations Manager**  
**David Snodgrass/ Plant Manager**  
**Tim Bishop/ Environmental Operator**

CONTACTED DURING INSPECTION: **No**

### AREA EVALUATIONS

(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)

<b>S</b>	PERMIT	<b>N</b>	FLOW MEASUREMENT	<b>N</b>	STORMWATER
<b>S</b>	RECORDS/REPORTS	<b>N</b>	LABORATORY	<b>N</b>	FACILITY SITE REVIEW
<b>S</b>	OPERATION & MAINTENANCE	<b>N</b>	EFFLUENT/RECEIVING WATER	<b>N</b>	SELF-MONITORING PROGRAM
<b>N</b>	SAMPLING	<b>N</b>	SLUDGE HANDLING/DISPOSAL	<b>S</b>	PRETREATMENT
<b>S</b>	OTHER: <b>IU</b>				

### SUMMARY OF FINDINGS

This was an industrial user inspection of:  
**Nidec Motor Corporation, 1000 S 2<sup>nd</sup> Ave, Paragould, AR 72450**



**No specific areas of concern were noted during the inspection.**

### GENERAL COMMENTS

This facility no longer discharges to the PLWC WWTP and recirculates the processed water throughout the plant. Only sanitary sewer exits the facility and is treated by the WWTP.

Inspection was performed as part of a Pretreatment Compliance Inspection. See the full PCI report for details.

Wes Klasky, Jonesboro Area Inspector, and Brent Walker, Inspector Supervisor, also participated in this inspection.

INSPECTOR'S SIGNATURE:  <b>Sarah Frasher</b>	DATE: <b>2/4/2022</b>
SUPERVISOR'S SIGNATURE:  <b>Brent L. Walker</b>	DATE: <b>11/4/2022</b>

## Industrial Site Visit

Name of Industry: Nidec Motor Corporation

Industry Contacts: David Snodgrass, Plant Manager; Tim Bishop, Environmental Operator

Type of Industry: Aluminum Die Caster

Date of Visit: 12/08/2021 13:46-14:20

- |     |  |   |                             |   |
|-----|--|---|-----------------------------|---|
| 1.  | Significant industrial user:                       | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |
| 2.  | Pretreatment equipment or procedures?              | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |
| 3.  | Pretreatment equipment maintained and operational? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |
| 4.  | Hazardous waste generated or stored?               | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |
| 5.  | Proper solid waste disposal?                       | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |
| 6.  | Solvent management/TTO control?                    | <input type="checkbox"/> Yes            | <input type="checkbox"/> No | <input checked="" type="checkbox"/> N/A |
| 7.  | Suitable sampling location?                        | <input type="checkbox"/> Yes            | <input type="checkbox"/> No | <input checked="" type="checkbox"/> N/A |
| 8.  | Appropriate self-monitoring procedures/equipment?  | <input type="checkbox"/> Yes            | <input type="checkbox"/> No | <input checked="" type="checkbox"/> N/A |
| 9.  | Adequate spill prevention?                         | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |
| 10. | Industry familiar with limits and requirements?    | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A            |

Additional Comments:

This facility no longer discharges to the PLWC WWTP and recirculates the processed water throughout the plant. Only sanitary sewer exits the facility and is treated by the WWTP.

Office of Water Quality Photographic Evidence Sheet

Location:	<b>Paragould Light, Water &amp; Cable</b>			
Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	
Time:	<b>14:10</b>		Photo #:	<b>1</b>
Witness:	<b>Wes Klasky and Brent Walker</b>		Photo #:	<b>1</b>
Description:	<b>Overview of the pretreatment area for Nidec Motor Corporation.</b>			



Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	
Time:	<b>14:00</b>		Photo #:	<b>2</b>
Witness:	<b>Wes Klasky and Brent Walker</b>		Photo #:	<b>2</b>
Description:	<b>View of the holding tank.</b>			



Office of Water Quality Photographic Evidence Sheet

Location:	<b>Paragould Light, Water &amp; Cable</b>			
Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	
Witness:	<b>Wes Klasky and Brent Walker</b>		Time:	<b>14:01</b>
Description:	<b>View of the DAF unit.</b>		Photo #:	<b>3</b>



Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	Time:	<b>14:03</b>
Witness:	<b>Wes Klasky and Brent Walker</b>		Photo #:	<b>4</b>	
Description:	<b>View of the Outfall pipe. Note this pipe is capped and not connected to the WWTP.</b>				



Office of Water Quality Photographic Evidence Sheet

Location:	<b>Paragould Light, Water &amp; Cable</b>			
Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	
Witness:	<b>Wes Klasky and Brent Walker</b>		Time:	<b>14:18</b>
Description:	<b>View of the pump station for Nidec Motor Corporation.</b>			



Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	
Witness:	<b>Wes Klasky and Brent Walker</b>		Time:	<b>14:15</b>
Description:	<b>View of the inside of the pump station.</b>			



Office of Water Quality Photographic Evidence Sheet

Location:	<b>Paragould Light, Water &amp; Cable</b>				
Photographer:	<b>Sarah Frasher</b>	Date:	<b>12/8/2021</b>	Time:	<b>14:17</b>
Witness:	<b>Wes Klasky and Brent Walker</b>			Photo #:	<b>7</b>
Description:	<b>View of the inside of the wet well.</b>				

