



ENVIRONMENTAL
QUALITY

OFFICE OF WATER QUALITY INSPECTION REPORT

AFIN: 28-00047	PERMIT #: AR0033766	DATE: 12/8/2021
COUNTY: 28 Greene	PDS #: 123343	MEDIA: WN
GPS LAT: 36.031471 LONG: -90.491622 LOCATION: Entrance		

FACILITY INFORMATION

NAME:
Paragould Light, Water & Cable
LOCATION:
401 Grant Lane
CITY:
Paragould

RESPONSIBLE OFFICIAL

NAME: / TITLE
Darrell Phillips / General Manager & CEO
COMPANY:
Paragould Light, Water & Cable
MAILING ADDRESS:
P.O. Box 9
CITY, STATE, ZIP:
Paragould AR 72451
PHONE & EXT: / FAX:
/
EMAIL:

CONTACTED DURING INSPECTION: **No**

INSPECTION INFORMATION

FACILITY TYPE: 1 - Municipal	INSPECTOR ID#: 112347 S - State		
FACILITY EVALUATION RATING: N	INSPECTION TYPE: Industrial User		
DATE(S): 12/8/2021	ENTRY TIME: 14:31	EXIT TIME: 15:26	PERMIT EFFECTIVE DATE: 3/1/2021
			PERMIT EXPIRATION DATE: 2/28/2026

FAYETTEVILLE SHALE RELATED: **N**

FAYETTEVILLE SHALE VIOLATIONS: **N**

INSPECTION PARTICIPANTS

NAME/TITLE/PHONE/FAX/EMAIL/ETC.:
Lisa Ellington, PhD/ Environmental Services Manager
David Romine, P.E./ WWTP Operations Manager
Andy Stickler/ Environmental Supervisor
Nick Evans/ Operator

AREA EVALUATIONS

(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)

S	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER
S	RECORDS/REPORTS	N	LABORATORY	N	FACILITY SITE REVIEW
S	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT
S	OTHER: IU				

SUMMARY OF FINDINGS

This was an industrial user inspection of:
DRiV Inc./ Tenneco Inc., 1601 Highway 49B, Paragould, AR 72450

No specific areas of concern were noted during the inspection.

GENERAL COMMENTS

Inspection was performed as part of a Pretreatment Compliance Inspection. See the full PCI report for details.

Wes Klasky, Jonesboro Area Inspector, and Brent Walker, Inspector Supervisor, also participated in this inspection.

INSPECTOR'S SIGNATURE:  **Sarah Frasher**

DATE: **2/4/2022**

SUPERVISOR'S SIGNATURE:  **Brent L. Walker**

DATE: **11/4/2022**

Industrial Site Visit

Name of Industry: DRiV Automotive

Industry Contacts: Andy Stickler, Environmental Supervisor; Nick Evans, Operator

Type of Industry: Metal finisher

Date of Visit: 12/8/2021

- | | | | | |
|-----|--|---|-----------------------------|---|
| 1. | Significant industrial user: | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 2. | Pretreatment equipment or procedures? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 3. | Pretreatment equipment maintained and operational? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 4. | Hazardous waste generated or stored? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 5. | Proper solid waste disposal? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 6. | Solvent management/TTO control? | <input type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> N/A |
| 7. | Suitable sampling location? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 8. | Appropriate self-monitoring procedures/equipment? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 9. | Adequate spill prevention? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 10. | Industry familiar with limits and requirements? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |

Additional Comments:

PLWC has a good working relationship with the industry contacts and facility is maintained appropriately.

Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable		
Photographer:	Sarah Frasher	Date:	12/8/2021
Witness:	Wes Klasky and Brent Walker	Time:	14:49
		Photo #:	1
Description:	View of the initial oil/water separator.		



Photographer:	Sarah Frasher	Date:	12/8/2021
Witness:	Wes Klasky and Brent Walker	Time:	14:49
		Photo #:	2
Description:	View of the inside of the oil/ water separator.		



Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable				
Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:50
Witness:	Wes Klasky and Brent Walker			Photo #:	3
Description:	View of the batch treatment tanks used for more concentrated water.				



Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:50
Witness:	Wes Klasky and Brent Walker			Photo #:	4
Description:	View of the inside of the batch treatment tank.				



Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable				
Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:55
Witness:	Wes Klasky and Brent Walker			Photo #:	5
Description:	View of the equalization tank.				



Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:55
Witness:	Wes Klasky and Brent Walker			Photo #:	6
Description:	View of the oil/water separator in the equalization tank.				



Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable				
Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:56
Witness:	Wes Klasky and Brent Walker			Photo #:	7
Description:	View of the inside of the equalization tank.				



Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:59
Witness:	Wes Klasky and Brent Walker			Photo #:	8
Description:	View of the clarifier.				



Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable				
Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:59
Witness:	Wes Klasky and Brent Walker			Photo #:	9
Description:	View of the skimmer arm and scum trough of the clarifier.				



Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:54
Witness:	Wes Klasky and Brent Walker			Photo #:	10
Description:	View of the sludge thickening tank.				



Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable				
Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	14:50
Witness:	Wes Klasky and Brent Walker			Photo #:	11
Description:	View of the filter press.				



Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	15:07
Witness:	Wes Klasky and Brent Walker			Photo #:	12
Description:	View of the sampling equipment for DRiV Automotive.				



Office of Water Quality Photographic Evidence Sheet

Location:	Paragould Light, Water & Cable				
Photographer:	Sarah Frasher	Date:	12/8/2021	Time:	15:07
Witness:	Wes Klasky and Brent Walker			Photo #:	13
Description:	View of the Outfall 001.				

