

# Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Siloam Springs

NPDES Permit No.: AR0020273

Monitoring Period (Month/Year): 04 / 2015

No Sanitary Sewer Overflows This Monitoring Period

## Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	NEAH-No Evidence Adverse Health/ Environmental Impact		CR-Creek/Stream/River (specify)
D-Debris			
E-Equipment Failure	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall		HR-Hand Rodded	GR-Ground Surface
RO-Roots		EN-Referred to Engineering	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
Basin 5	106	04/27/2015	04/27/2015	2000	Unknown	NEAH	EC, HC	GR

Signature of Cognizant or Ranking Official \_\_\_\_\_

Date 5/19/15

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."