

# Sanitary Sewer Overflow (SSO) Monthly Report

**Facility Name:** Siloam Springs     
 **NPDES Permit No.:** AR0020273     
 **Monitoring Period (Month/Year):** 08 / 2015

No Sanitary Sewer Overflows This Monitoring Period

## Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
<b>CO-Construction</b>	D-Debris	NEAH-No Evidence Adverse Health/ Environmental Impact	CR-Creek/Stream/River (specify)
<b>E-Equipment Failure</b>	G-Grease	OEHC-Observed or Evidence of Human Contact	DI-Ditch
<b>HC-Hydro Clean</b>	LF-Line Failure	EFK-Evidence of Fish Kill	DR-Drop Inlet
<b>R-Rainfall</b>	RG-Roots / Grease	HR-Hand Rodded	GR-Ground Surface
<b>RO-Roots</b>	V-Vandalism	EN-Referred to Engineering	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
Basin 5	31	8/7/2015	8/7/15	50	CO	NEAH	EC	CR

Signature of Cognizant or Ranking Official

Date: 9/01/2015

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.