


## Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Siloam Springs NPDES Permit No.: AR0020273 Monitoring Period (Month/Year): 11 /2013

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/ Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots / Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
Basin 6	62	11/13/2013	11/13/2013	3	D	NEAH	HC, EC	GR
Basin 3	47	11/17/2013	11/17/2013	40	D	NEAH	HC, EC	GR
Tank overflow 975 Anderson Avenue Wastewater Facility			11/24/2013	300	E	NEAH	EC, EN	GR
	See attached phone log DMR							



12/20/2013

**Signature of Cognizant or Ranking Official**

**Date**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."



CITY OF  
**Siloam Springs**  
*It's a natural.*

## PHONE CONTACT LOG

Name of Caller: Tom Myers

Company: City of Siloam Springs

Date/Time Call Made/Received: 11/25/2013

14:28 p.m.

Call Received By: Deborah Gerst

Company: ADEQ

Comments: Tom called to inform ADEQ that RAS/WAS recirculation tank overflowed tank wall due to telescoping valve failure Sunday 11/24/2013. Alarm at 14:30 and responded immediately to correct problem. Estimated 300 gallons on the ground surrounding tank that was lined. Telescoping valve system repaired and placed back into service. Called and notified ADEQ representative Deborah Gerst 11/25/2013 at 14:10 to report incident. Deborah assigned number to notification of in-plant overflow of tank. No NEAH occurred.

This information will be attached to the monthly report for November.

Engineering firm that designed system was contacted to determine problem that can be corrected.

Electrical System Programmer is scheduled to come and set new fail limits on telescoping valves.

Tom thanked Deborah for her time.

RE: Wastewater Plant  
NPDES Permit No. AR0020273

Name/Title	Division	Phone/E-Mail
Gerst, Deborah Administrative Specialist III	Water	(501) 682-0638 Email: gerst@adeq.state.ar.us

PLACE STICKER AT TOP OF ENVELOPE TO THE RIGHT  
OF THE RETURN ADDRESS, FOLD AT DOTTED LINE



7013 1090 0002 3055 5502

Hasler

FIRST-CLASS MAIL


12/23/2013

US POSTAGE

\$06.97<sup>0</sup>



ZIP 72761  
011D11628725



1000

72118

**CITY OF SILOAM SPRINGS**

P.O. Box 80  
Siloam Springs, AR 72761

AR Dept Environmental Quality  
NPDES Enforcement Section  
5301 Northshore Drive  
North Little Rock, AR 72118-5317