


Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Siloam Springs NPDES Permit No.: AR0020273 Monitoring Period (Month/Year): 10 / 2013

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/ Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots / Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
Basin 3	89	10/11/2013	10/11/2013	50	G	NEAH	HC-EC	GR
Please Note: A spill happened at Wastewater Facility associated to Final Clarifier Telescoping Valve electrical failure. When called in to report it was recorded as SSO. Narrative is reported on October DMR along with attached email to ADEQ staff representative Deborah Gerst.								



11/20/2013

Signature of Cognizant or Ranking Official Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."



CITY OF
Siloam Springs
It's a natural

PHONE CONTACT LOG

Name of Caller: Tom Myers

Company: City of Siloam Springs

Date/Time Call Made/Received: 10/25/2013

14:28 p.m.

Call Received By: Deborah Gerst

Company: ADEQ


Comments: Tom called to inform ADEQ that RAS/WAS recirculation tank overflowed tank wall due to telescoping valve failure. Alarm at 14:05 and responded immediately to correct problem. Estimated 400-500 gallons on the ground surrounding tank that was limed. Telescoping valve system repaired and placed back into service. Called and notified ADEQ representative Deborah Gerst 10/25/2013 at 14:28 to report incident. Deborah assigned number 94ADE5B4 to notification of in-plant overflow of tank. No NEAH occurred.

This information will be attached to the monthly report for October.
Tom thanked Deborah for her time.

RE: Wastewater Plant
NPDES Permit No. AR0020273

Name/Title	Division	Phone/E-Mail
Gerst, Deborah Administrative Specialist III	Water	(501) 682-0638 Email: gerst@adeq.state.ar.us

CERTIFIED MAIL™



7013 1090 0002 3055 5472



P.O. Box
Siloam Springs, AR 72761

Hasler

FIRST-CLASS MAIL

11/20/2013

US POSTAGE

\$06.97⁰⁰




ZIP 72761
011D11628725



UNITED STATES
POSTAL SERVICE

1000



72118

U.S. POSTAGE
PAID
SILOAM SPRINGS, AR
72761
NOV 20, 13
AMOUNT

\$0.00
00055495-12

AR Dept Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317

