

Sanitary Sewer Overflow Monthly Report

Facility Name: Arkadelphia Water Permit Number: AR0020625 Reporting Period (Month/Year): Aug-2012

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
B-Equipment Failure	G-Grease			
HC-Hydro Clean	LF-Line Failure/Break	BFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
		08-03-2012	08-06-12	1/2 Million	LF	NEAH	WO	GR

Daniel Thomson

09-21-2012

Signature of Cognizant or Ranking Official Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."



ARKADELPHIA
WATER UTILITIES
700 Clay Street • P. O. Box 495
Arkadelphia, Arkansas 71923

LITTLE ROCK AR 720

22 SEP 2012



02 1P \$ 000.65⁰
0003925991 SEP 21 2012
MAILED FROM ZIP CODE 71923

Arkansas Department of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317

72118531799

