Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Whitises NPDES Permit No.: ARODES Monitoring Period (Month/Year): 03/ 2016

No Sanitary Sewer Overflows This Monitoring Period

Causa(s)	02222	Summary Report Code Descri	ptions		
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D -Debris	NEAH-No Evidence Adverse Health/ Environmental. Impact		CR-Creek/Stream/River (specify)	
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	FC Frank		
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	EC-Environmental Cleanup	DI-Ditch	
R-Rainfall	RG-Roots / Grease	EFR-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet	
RO-Roots	V-Vandalism		HR-Hand Rodded	GR-Ground Surface	
110 110013	V-Validatistit		EN-Referred to Engineering	PA-Paved Area	
	L		PN-Public Notification	CB-Contained in Building	

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
								·
	}						 	
								
						—		
					 			
				·				
]	1	-

Daviel ?	Thomeson
----------	----------

03/22/2016

Signature of Cognizant or Ranking Official

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."





Arkansas Department of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317