

Facility Name: Van Buren/ South Park

### Sanitary Sewer Overflow Monthly Report

Permit Number: AR0021482 Reporting Period (Month/Year): January 2018

**No Sanitary Sewer Overflows. This Monitoring Period**

Cause(s) of SSO		SSO Impact		Summary Report Code Descriptions		Actions Taken		Ultimate Discharge Location	
CO-Construction	D-Debris	NEAF- No Evidence of Adverse Health or Environmental Impact		WO- Work Order		CR- Creek/Stream/River (please specify)			
E-Equipment Failure	G-Grease	OFFC- Observed or Evidence of Human Contact		EC- Environmental Cleanup		DI- Ditch			
HC-Hydro Clean	LF-Line Failure/Break	BFK- Evidence of Fish Kill		HC-Hydro Cleaned		DR- Drop Inlet			
R-Rainfall	RG-Roofs & Grease			HR- Hard Rodded		GR- Ground Surface			
RO-Roots	V-Vandalism			EN- Referred to Engineering		PA- Paved Area			
				PN- Public Notification		CB- Contained in Building			

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
City Park	SH10005	1-22	1-22	1000	E	Near	WO	GR/OT
1711 Cedar	Clear out	1-22	1-22	75	G	Near	HC	GR/OT
1410 N 26th	50X1305	1-22	1-22	50	G	Near	HC	PA/CG
11 Bow Air	50X0425	1-23	1-23	20	RL	Near	HC	GR/OT

**Signature of Cognizant or Ranking Official** \_\_\_\_\_ **Date** 2/22/2018

I certify under penalty of law that this document and all attachments were prepared by me or under my direct supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.