

CITY OF VAN BUREN Sanitary Sewer Overflow Monthly Report

Facility Name: MAIN PLANT Permit Number: AR0021482 Reporting Period (Month/Year): December 2012

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease		EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease	EFK-Evidence of Fish Kill	HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
<u>1504 N. H. 115</u>	<u>92-95</u>	<u>12-30</u>	<u>12-30</u>	<u>350</u>	<u>D-RG</u>	<u>NEAH</u>	<u>HC</u>	<u>DI-GR-CB</u>

Steve [Signature]

1-22-13

Signature of Cognizant or Ranking Official

Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality
 NPDES Enforcement Section
 5301 Northshore Drive
 North Little Rock, AR 72118

RE: NPDES Permit No: AR0021482 Discharge Number: AFIN 17-00062

Facility: Van Buren Main Plant

Address: 1401 Port Road

City: Van Buren State: AR Zip: 72954

Contact: James Dunn / Steve Dufresne Phone: 479-474-5067


Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
December 2012	BODs-30day Ave	549 lbs/d	38 mg/L	30 mg/L
	TSS-30day Ave	178 lbs/d	33 mg/L	30 mg/L

We feel this problem was due to:
Low solids concentration in aeration basin & poor settling

We plan on correcting the problem in this manner:
Raising solids concentration in aeration basin


(Had loads of sludge hauled in from our North Plant to seed 162,000 gallons & now pumping seed (sludge) in from E. O basin)

Time estimated that it will take to correct problem:
2 weeks

Sincerely,

 Authorized Signature


1-16-2013
 Date

VAN BUREN MUNICIPAL UTILITIES
2806 BRYAN RD.
P.O. DRAWER 1269
VAN BUREN, AR 72957



Recycle



UNITED STATES POSTAGE
PITNEY BOWES
02 1P \$ 003.30⁰
0003195454 JAN 22 2013
MAILED FROM ZIP CODE 72956

Arkansas Dept. Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317

