


CITY OF VAN BUREN Sanitary Sewer Overflow Monthly Report

Facility Name: MAIN PLANT Permit Number: ARO021482 Reporting Period(Month/Year): July 2012

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions			
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned
R-Rainfall	RG-Roots & Grease	HR-Hand Rodded	DR-Drop Inlet
RO-Roots	V-Vandalism	EN-Referred to Engineering	GR-Ground Surface
		PN-Public Notification	PA-Paved Area
			CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location



August 16, 2012
Date

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."