## CITY OFFICIALS:

DICKIE KENNEMORE, MAYOR MIKE GIBSON, MUNICIPAL JUDGE DON BETTERTON, CITY ATTORNEY LYNDA WELLS, CLERK / TREASURER



CITY COUNCIL:

JOE GUY
OTTIS RAPER
JEANETTE WALKER
LINDA WATSON
LUTHER WHITFIELD
GENE COX

March 11, 2014

Arkansas Department of Environmental Quality NPDES Enforcement Section 5301 N. Shore DR. North Little Rock, Arkansas

RE: NPDES PERMIT NO. AR0021580
Discharge Monitoring Report for February, 2014

72118

Enclosed is the Discharge Monitoring Report for the City of Osceola for the month February, 2014.

The permit conditions were met during the month February 2014, for BOD<sup>5</sup>, TSS, PH, Fecal Coliform, Dissolved Oxygen (DO). A total of 09 samples were taken for each during the month of February, 2014

One sample was taken during the month of February, 2014 for Phosphorus, total (as P) and One sample was taken during the month of February, 2014 for Nitrite plus nitrate total 1 det. (as N)

No samples were taken the weeks ending February 01, 2014 and March 01, 2014 due to no flow from the wastewater treatment plant.

Also enclosed with the regular February, 2014 (DMR) is the Sanitary Sewer Overflow Monthly Report, (SSO), with 01 overflow's for the month of February, 2014.

Thanks.

James N. Carlock WWTP SUPT.

ames of Carlock

Enclosure

303 West Hale Avenue - P.O. Box 443 - Osceola, AR 72370
(870) 563-5245
COMBINING INDUSTRY WITH AGRICULTURE FOR PROGRESS
AN EQUAL OPPORTUNITY EMPLOYER

## Sanitary Sewer Overflow Monthly Report

Permit Number: AR0021580 Reporting Period(Month/Year): FEBRUARY Facility Name: OSCEOLA CITY OF 2014 ☐ No Sanitary Sewer Overflows This Monitoring Period

i		Summary Report Code Descriptions		Title of Discharge Location	
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental	WO-Work Order	CR-Creek/Stream/River (please specify)	
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup HC-Hydro Cleaned	DI-Ditch DR-Drop Inlet	
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill		GR-Ground Surface	
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	PA-Paved Area	
RO-Roots	V-Vandalism		EN-Referred to Engineering PN-Public Notification	CB-Contained in Building	

Location	Manhole#	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
	#/	2-5-14	2-5-14	HNKNOWN	POWER BUTAGE	NEAH	HC	PA
WEST QuINN					ICE-STORM			
		<del>- </del>			POWER LINE			
					DOWN /			· · · · · · · · · · · · · · · · · · ·
		<u> </u>						
		<del>                                     </del>			<u> </u>			
		<del>                                     </del>						
			<del>                                     </del>					
			<del> </del>	+				
				<u> </u>				
				<del></del>	-	<del> </del>		
					<del> </del>	<del> </del>		
						<del> </del>	<del> </del>	
							March 11,	2014

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

City of Osceola @ James Carlock P O Eox 443 303 West Hale Osceola, AR 72370



7012 3050 0000 1110 1703

Hasler

03/11/2014 US|ROSTAGE

\$07.129



ZIP 72370 011D11627215



1000





U.S. POSTAGE PAID USCEULH.HK 72370 MAR II. 14 AMOUNT

72118

ADEQ

Arkansas Department of Environmental Quality 5301 N. Shore DR.

North Little Rock, Arkansas 72118-5317