## CITY OFFICIALS:

DICKIE KENNEMORE, MAYOR MIKE GIBSON, MUNICIPAL JUDGE DON BETTERTON, CITY ATTORNEY LYNDA WELLS, CLERK / TREASURER



CITY COUNCIL:

JOE GUY
OTTIS RAPER
JEANETTE WALKER
LINDA WATSON
LUTHER WHITFIELD
GENE COX

August 12, 2013

Arkansas Department of Environmental Quality NPDES Enforcement Section 5301 N. Shore DR. North Little Rock, Arkansas

## RE: NPDES PERMIT NO. AR0021580 Discharge Monitoring Report for JULY, 2013

Enclosed is the Discharge Monitoring Report for the City of Osceola for the month July, 2013.

The permit conditions were met during the month July 2013, for BOD<sup>5</sup>, TSS, PH, Fecal Coliform, Dissolved Oxygen (DO). A total of 06 samples were taken for each during the month of July, 2013

72118

One sample was taken during the month of July, 2013 for Phosphorus, total (as P) and One sample was taken during the month of July, 2013 for Nitrite plus nitrate total 1 det. (as N)

James M. Carlock

Also enclosed with the regular July, 2013 (DMR) is the Sanitary Sewer Overflow Monthly Report, (SSO), with 00 overflow's for the month of July, 2013.

Thanks,

James N. Carlock

WWTP SUPT.

Enclosure

## Sanitary Sewer Overflow Monthly Report

Facility Name: OSCEOLA CITY OF Permit Number: AR0021580 Reporting Period(Month/Year): JULY 2013

No Sanitary Sewer Overflows This Monitoring Period

		Summary Report Code Descriptions	S		
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental	WO-Work Order	CR-Creek/Stream/River (please specify)	
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup HC-Hydro Cleaned	DI-Ditch DR-Drop Inlet	
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill		GR-Ground Surface	
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded EN-Referred to Engineering	PA-Paved Area	
RO-Roots	V-Vandalism		PN-Public Notification	CB-Contained in Building	

Location	Manhole#	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
<u></u>	<del> </del>							
	<del>-  </del>							
				<u> </u>				
			<u> </u>					
					<b></b>			
						<del></del>	<del>                                     </del>	
							<del></del>	
						<del></del>		
		<del> </del>			<u> </u>	<u> </u>		+
7			2		1		August 1	2 2013

August 12,2

Date

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the properly gather and evaluate the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

## Sanitary Sewer Overflow Monthly Report

Permit Number: AR0021580 Reporting Period(Month/Year): JULY 2013 Facility Name: OSCEOLA CITY OF No Sanitary Sewer Overflows This Monitoring Period

		Summary Report Code Descriptions	s		
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental	WO-Work Order	CR-Creek/Stream/River (please specify)	
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch DR-Drop Inlet	
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DK-Drop Inici	
2 2 : 6 !!	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface	
R-Rainfall	V-Vandalism		EN-Referred to Engineering	PA-Paved Area	
RO-Roots	V-Vandalishi		PN-Public Notification	CB-Contained in Building	

Location	Manhole#	Start Date of SSO	End Date of SSO	Estimated Volume (in gailons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
			<del>                                     </del>					
		+			•			
			<del> </del>		·····*			
				<del>\</del>				
						<u> </u>	<u> </u>	
					<u> </u>			ļ
			<del></del>					
					<del> </del>	<del>                                     </del>		
						+	<del> </del>	1
							<del> </del>	<del> </del>
								<u> </u>
			<del></del>					

August 12,2013

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel Signature of Cognizant or Ranking Official properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

City of Osceola @ James Carlock P O Box 443 303 West Hale Osceola, AR 72370



Hasler

08/12/2013 USIROSTAGE

\$06.779



ZIP 72370 011D11627215



**ADEQ** 

Arkansas Department of Environmental Quality 5301 N. Shore DR.

North Little Rock, Arkansas 72118-5317

Timpophanicine Material printer