

# NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality  
NPDES Enforcement Section  
5301 Northshore Drive  
North Little Rock, AR 72118

**RE: NPDES Permit No:** AR0021661      **Discharge Number:** A-001-Monthly

**Facility:** Cabot Water & Wastewater Treatment Facility

**Address:** 76 Marshall Lane

**City:** Cabot      **State:** AR      **Zip:** 72023

**Contact:** Tim Joyner      **Phone:** 501-605-1740

Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
Aug. 1st - Aug. 15th	Ammonia		3.2 mg/L, 7.1 mg/L	2.1 mg/L mo avg / 5.2 mg/L 7day Avg

We feel this problem was due to:

Supernatant water from sludge lagoon had high ammonia

We plan on correcting the problem in this manner:

Overflow gate was raised to hold Sludge lagoon water until ammonia levels drop, (cooler temps)


Time estimated that it will take to correct the problem/s:

Ammonia returned to compliance level on August 16th.

Sincerely,

Authorized Signature

Date



9/13/18