

# ADEQ

ARKANSAS  
Department of Environmental Quality

January 22, 2014

Tim Joyner  
Cabot Water and Wastewater Commission  
Cabot Wastewater Treatment Facility  
P.O. Box 1287  
Cabot, AR 72023

RE: NPDES Permit Number AR0021661, AFIN 43-00059,  
Deficient Discharge Monitoring Report

Dear Mr. Joyner:

The Discharge Monitoring Report (DMR) submitted for 12/31/2013 Monitoring Period, Discharge Number TX1-Q has been received by the Department. Upon review, I noticed that you failed to submit parameter values for the parameters I have highlighted on the DMRs I provided. If analysis was not conducted for a parameter during a given monitoring period please write an "E" in the highlighted section for that parameter. If a parameter value was required by your permit but analysis was not conducted, please provide a Non-Compliance Report detailing why analysis was not conducted.

Please submit the corrected DMRs, clearly marked as "Corrected Copy", with the changes highlighted. Submit two legible copies of the corrected DMRs with an **original signature and date (RE-SIGN and RE-DATE)** by the Cognizant Official. These corrected copies should be received by the Department no later than **January 29, 2014**.

Thank you for your attention to this matter. Please refer to NPDES Permit Number AR0021661 and AFIN 43-00059 in any written correspondence to this Department. Should you have any questions, feel free to contact me at 501-682-0667 or you may e-mail me at [bolenbaum@adeq.state.ar.us](mailto:bolenbaum@adeq.state.ar.us).

Sincerely,



Michelle Bolenbaugh  
Enforcement Analyst  
Water Division, Enforcement Branch