CONFIRMATION NUMBER

48ACA744-8A6A-4BAA-A36B-D43E45A9F139

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

		Close this window	v Print this page	
		24-Hour Sanitary Se	wer Overflow Report	:
SSO ID#: 48ACA744-8	A6A-4BAA-A36B-D43E45A9F13	_	aci overnou report	
Date Sent: 10/11/2014				
ØSSO ○Bypass ○)Upset			•
Facility Permit Number: AR0021750 Date Overflow Began: 10/10/2014		Facility name: Time:		Massard :10:30 pm
Date Overflow Ended:	10/10/2014		ime:	12:15 pm
Location:	1601 south 74th Stre	et, manhole no. RLO1-0)730	
			,	
	(Give address, manhole i	number-if numbered. Incl		tch, stream, storm sewer, building, other)
Type of Overflow			Cause of Overflow	
(﴿☑) Manhole Overflow . (☐) Lift Station Overflow			(()) I & I - Rainfall	
			(O) Cooper	
() Main Line Overflow () Service Line Overflow			(◯) Grease (◯) Debris	
(Other Overflow Type:			(O) Equipment Failure	·
(Other Overnow Ty	•	licted)	(C) Equipment Failure (C) Construction	
Volume:	(Enter overflow type if not i	isted)	() Vandalism	
Volume.	5,250		(O) Power Failure	
	(Give an estimate in gallons) SSO Affected Private Property (ground)		(O) Line Failure/Break	
Impact of SSO Event:	330 Allected Private Property (ground)		(②) Other Cause: Wet weather rainfall	
		•	(4)	
Action Taken - Check all t		nd any plans to remediate	. 1 & 1)	
(Short term and long-term action, including clean-up and any plans to remedia: (()) Machine rodded (()) Disinfected and Deo			•	•
(O) Jet-Vac	_'			
) Hand rodded () Spread Lime on Affe		ted Area		
() Used Generator To Power Pumps/Equipment () Public Notification				•
Other: Describe		-,		
(O)				•
Environmental Damage				
(O) OEHC - Observed	or Evidence of Human Contact	(⊘) NEAH - No Ev	ridence of Adverse Health/Environmen	tal Impact
(O) OEEI - Observed of	r Evidence of Environmental Im	pact (()) EFK - Evident	ce of Fish Kill	
				·
Reported By Steve Par	ke Title Director of Utilitie	s Telephone Number ((479) 	i
				•
Additional Comments			;	