

CONFIRMATION NUMBER

5279AD9E-CEB8-4920-840E-708C8FDFB8F7

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5279AD9E-CEB8-4920-840E-708C8FDFB8F7

Date Sent: 10/29/2014

SSO Bypass Upset

Facility Permit Number:	AR0021750	Facility name:	Massard WWTP
Date Overflow Began:	10/29/2014	Time:	9:16 am
Date Overflow Ended:	10/29/2014	Time:	10:03 am

Location: **4219 South 89th Street**
4301 South 89th Street, 4307 South 89th Street
M002 - 0250 to 0240 Main line blockage causing backup into three structures.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: **sewer backup into buildings**
(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **47**
(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments: **Cleanup Scheduled**
 if Needed: