

CONFIRMATION NUMBER

F13734D9-49F5-4CC9-BB58-69AFBE92FD82

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: F13734D9-49F5-4CC9-BB58-69AFBE92FD82
Date Sent: 9/16/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: **AR0033278**
 Date Overflow Began: **9/15/2015**
 Date Overflow Ended: **9/15/2015**
 Location: **1305 Willow Brook Circle, 2008-0165, ditch**

Facility name: **P Street**
 Time: **3:36 pm**
 Time: **5:21 pm**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **850**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **repair**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

0FB4D59A-4AB4-4A52-92CF-B0AC57C1D35E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0FB4D59A-4AB4-4A52-92CF-B0AC57C1D35E

Date Sent: 9/15/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

9/14/2015

Time:

8:55 pm

Date Overflow Ended:

9/14/2015

Time:

11:50 pm

Location:

9424 Belhaven View, Z005-1070, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

4375

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

00D47739-B813-481C-AD5C-946BB92EC4D7

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 00D47739-B813-481C-AD5C-946BB92EC4D7

Date Sent: 9/12/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

9/11/2015

9/11/2015

3011 Blackburn Street, P008-1855 to 1850, ditch

Facility name:

Time:

Time:

P Street

12:40 pm

6:00 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

1550

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe repaired
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

AD3FCC91-1D5A-46EE-A0BA-8CD872DA3BD7

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: AD3FCC91-1D5A-46EE-A0BA-8CD872DA3BD7

Date Sent: 9/9/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

9/9/2015

9/9/2015

Facility name:

Time:

Time:

Massard

1:20 pm

1:59 pm

3001 North Albert Pike Avenue, S009-1500, yard and building

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

975

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0C9FEF3E-6C82-4D86-BCDA-297D16D4FEBC

Date Sent: 9/6/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: AR0033278

Facility name:

P Street

Date Overflow Began: 9/5/2015

Time:

9:25 am

Date Overflow Ended: 9/5/2015

Time:

11:15 am

Location:

3000 Irving Street, W001-1140 to 1120, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

260

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2274

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

A71A85D0-8467-4433-80B9-1B7E51887F2B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A71A85D0-8467-4433-80B9-1B7E51887F2B

Date Sent: 9/4/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

9/3/2015

9/3/2015

2823 Memphis, MC07-1100,ditch

Facility name:

Time:

Time:

P Street

8:40 pm

10:00 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

840

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

1636E325-CC40-4379-B895-733D6F754328

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1636E325-CC40-4379-B895-733D6F754328
Date Sent: 9/2/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
9/2/2015
9/2/2015

Facility name:
 Time:
 Time:

P Street
9:05 am
9:50 am

4709 South 32nd, 2001-2540, ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **45**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

Monthly SSO Report September 2015

Permit Number	Manhole Number	Location	Receiving Water	Duration Min.	Cause	Volume (Gallons)	Component	Date Overflow Started	Date Overflow Stopped	Started	Stopped	Steps Taken
AR0021750	S009-1500	3001 North Albert Pike Avenue	yard and building	39	Roots, Grease	975	Manhole	09/09/2015	09/09/15	1:20 PM	1:59 PM	Machine Rodded
AR0033278	Z001-2540	4709 South 32nd	ditch	45	Grease	45	Manhole	09/02/2015	09/02/15	9:05 AM	9:50 AM	Jet-Vac
AR0033278	MC07-1100	2823 Memphis	ditch	840	Roots	840	Manhole	09/03/2015	09/03/15	8:00 PM	10:00 AM	Jet-Vac, Dsinfected and Deodorized
AR0033278	W001-1140 to 1120	3000 Irving Street	yard	130	Roots, Grease	260	Service line	09/05/2015	09/05/15	9:25 AM	11:15 AM	Power Rod, Dsinfected and Deodorized
AR0033278	P008-1855 to 1850	3011 Blackburn Street	ditch	310	Line Failure/Break	1550	Main Line	09/11/2015	09/11/15	12:40 PM	5:30 PM	Rpaired, Dsinfected and Deodorized
AR0033278	Z005-1070	9424 Belhaven View	paved area	175	Roots	4375	Manhole	09/14/2015	09/14/15	8:55 PM	11:50 PM	Jet-Vac, Dsinfected and Deodorized
AR0033278	Z008-0165	1305 Willow Brook Circle	ditch	85	Construction	850	Manhole	09/15/2015	09/15/15	3:36 PM	5:21 PM	Repair, Dsinfected and Deodorized