

Discharge Monitoring Report (DMR)

AR0021750 DMR SSOs December 2023

Print Date: 1/3/2024

Print Time: 4:57 pm

Permit Number	Date SSO Started	Time SSO Started	Date SSO Stopped	Time SSO Stopped	Date SSO Reported	Location	Pipe Description	Manhole	Where SSO Went Into	Watershed	Type of SSO	Cause of SSO	Environmental Damage	Duration in Min.	Volume (Gallons)	Impact of SSO Incident	Steps Taken	Internal SSO ID	Web Confirmation Number
AR0021750																			
AR0021750	12/05/2023	7:57 am	12/05/2023	9:25 am	12/05/2023	8800 Copper Oaks Ln	PS-024 to M004-0490		Storm Drain Yard Paved Area Arkansas River	City of Fort Smith to Arkansas River	Force Main	Line Break	NEAH	88	2,200	Receiving Water (Riv. Str)	Schedule Repair,Repair,Scheduled Cleanup,Disinfection Performed	23-0259	7341ddd2-3321-476f-9c73-d23be186df3b
AR0021750	12/07/2023	11:57 am	12/07/2023	2:27 pm	12/07/2023	6003 Chippewa Trl	S002-0850 to S002-0840	S002-0850	Yard	N/A	Manhole	Roots	NEAH	150	3,000	Private PPTY (Ground)	Jet Clean,,Scheduled Cleanup,Disinfection Performed	23-0260	e313d23b-f2ba-4604-9765-af64a2401bcb
AR0021750	12/18/2023	12:33 pm	12/18/2023	1:35 pm	12/18/2023	6003 Chippewa Trl	S002-0850 to S002-0840	S002-0850	Yard	N/A	Manhole	Roots	NEAH	62	310	Private PPTY (Ground)	Power Rod,,Scheduled Cleanup,Disinfection Performed	23-0266	3ad36d3a-cb0b-45ce-b65d-c39b6aab70b1

3 TOTAL OVERFLOWS

5,510 TOTAL GALLONS SPILLED