

**Discharge Monitoring Report (DMR)**

Print Date: 3/18/2024

AR0021750 DMR SSOs February 2024

Print Time: 9:19 am

Permit Number	Date SSO Started	Time SSO Started	Date SSO Stopped	Time SSO Stopped	Date SSO Reported	Location	Pipe Description	Manhole	Where SSO Went Into	Watershed	Type of SSO	Cause of SSO	Environmental Damage	Duration in Min.	Volume (Gallons)	Impact of SSO Incident	Steps Taken	Internal SSO ID	Web Confirmation Number
<b>AR0021750</b>																			
AR0021750	02/01/2024	2:46 pm	02/01/2024	3:15 pm	02/01/2024	1607 S Albert Pike Ave	S003-1380 to S003-1373		paved Area	N/A	Service Line	Debris	NEAH	29	29	Private PPTY (Ground)	Power Jet,,Immediate Cleanup,Disinfection Performed	24-0022	e979e25c-2a07-41ce-8ae4-0bd03544459d
AR0021750	02/06/2024	4:35 pm	02/06/2024	5:20 pm	02/07/2024	4725 N N St	S007-1105 to S007-1100		Yard	N/A	Service Line	Debris	NEAH	45	90	Private PPTY (Ground)	Power Jet,,Scheduled Cleanup,Disinfection Performed	24-0028	080c80bc-ddf2-4786-82d6-d1bab7c1ceaf
AR0021750	02/08/2024	12:35 pm	02/08/2024	1:15 pm	02/08/2024	4401 Kinkead Ave	S006-1160 to S006-1130		Yard	N/A	Service Line	Grease	NEAH	40	40	Private PPTY (Ground)	Power Jet,,Scheduled Cleanup,Disinfection Performed	24-0029	6486f2b4-8334-4150-ab48-f4e7397debad
AR0021750	02/08/2024	12:30 pm	02/08/2024	1:15 pm	02/08/2024	612 N 44th St	S006-1160 to S006-1130		Yard	N/A	Service Line	Grease	NEAH	45	90	Private PPTY (Ground)	Power Jet,,Scheduled Cleanup,Disinfection Performed	24-0030	45b5785e-7744-48c8-a4f4-aa4dcd1e7d04

**4 TOTAL OVERFLOWS**

**249 TOTAL GALLONS SPILLED**