

**Discharge Monitoring Report (DMR)**

AR0021750 DMR SSOs June 2021

Print Date: 7/12/2021

Print Time: 8:16 am

Permit Number	Date SSO Started	Time SSO Started	Date SSO Stopped	Time SSO Stopped	Date SSO Reported	Location	Pipe Description	Manhole	Where SSO Went Into	Watershed	Type of SSO	Cause of SSO	Environmental Damage	Duration in Min.	Volume (Gallons)	Impact of SSO Incident	Steps Taken	Internal SSO ID	Web Confirmation Number
<b>AR0021750</b>																			
AR0021750	06/17/2021	8:30 am	06/17/2021	10:50 am	06/17/2021	9 Riverlyn Ter	RL01-0140 to RL01-0130	RL01-0140	Yared, River, stream, Creek	City of Fort Smith to Arkansas River	Manhole	Other	NEAH	140	7,000	Receiving Water (Riv, Str)	None Indicated,,Scheduled Cleanup,Disinfection Performed	21-0183	28a40127-4194-4795-bbca-cbd582894e9e
AR0021750	06/17/2021	8:30 am	06/17/2021	10:50 am	06/17/2021	5 Riverlyn Ter	RL01-0110 to RL01-0100	RL01-0110	River, Stream, Creek	City of Fort Smith to Arkansas River	Manhole	Other	NEAH	140	21,000	Receiving Water (Riv, Str)	None Indicated,,Scheduled Cleanup,No Disinfection Performed	21-0184	d76221ae-8796-4fb8-8edb-c28e50a96824
AR0021750	06/18/2021	5:21 pm	06/19/2021	11:40 am	06/19/2021	4013 S 89th St	M002-0280 to M002-0270		Yard	N/A	Service Line	Line Break	NEAH	1,099	1,099	Private PPTY (Ground)	None Indicated,,Scheduled Cleanup,No Disinfection Performed	21-0186	0f9cb015-a403-492c-84d1-c3e3a8d97ac6
AR0021750	06/28/2021	2:29 pm	06/28/2021	2:55 pm	06/29/2021	4034 Rogers Ave	S003-1340 to S003-1330	S003-1340	Paved Area	N/A	Manhole	Grease	NEAH	25	125	Public Land (Ground)	Jet Clean,,Scheduled Cleanup,Disinfection Performed	21-0192	ac6cac4f-cd87-4e21-bfd7-a0c0eacba40e
<b>4 TOTAL OVERFLOWS</b>										<b>29,224 TOTAL GALLONS SPILLED</b>									