

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: City Corporation NPDES Permit No: AR0021768 Monitoring Period (Month/Year): August / 2016

[X] No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO Construction E Equipment Failure R Rainfall RO Roots	D Debris G Grease LF Line Failure V Vandalism	NEAH No Evidence Adverse Health / Environmental Impact OEHC Observed or Evidence of Human Contact OEEI Observed or Evidence of Environmental Impact EFK Evidence of Fish Kill	EC Environmental Cleanup HC Hydro Cleaned HR Hand Rodded	CR Creek / String / River (specify) DI Ditch DR Drop Inlet GR Ground Surface PA Paved Area CB Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location



 Signature of Cognizant or Ranking Official

9-7-16

 Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Mail together with DMR submission NO LATER THAN THE 25th OF THE MONTH FOLLOWING THE MONITORING PERIOD to:
 ADEQ Office of Water Quality, 5301 Northshore Drive, North Little Rock, AR 72118