

JUNE
20 15

MARION DMR INFORMATION

EFF DATA											
DAYS	FLOW RA MGD	EFF DO MG/L	EFF PH SU	EFF NH3 MG/L	EFF NH3 LBS	EFF CBOC MG/L	EFF CBOC LBS	EFF TSS MG/L	EFF TSS LBS	EFF CL RE MG/L	EFF FECAL GEO
1	2.20										
2	2.40	6.2	7	1.24	24.82			14	280.22	0	73
3	2.40			1.12	22.42		7	140.11	14	280.22	0 70.00
4	2.30			1	19.18		9	172.64	20	383.64	0 82.00
5	2.30										
6	2.10										
7	2.10										
8	2.10										
9	2.10	6.2	7	1.55	27.15			30	525.42	0	179
10	1.80			1.95	29.27		13	195.16	31	465.37	0 345.00
11	1.80			1.13	16.96		15	225.18	29	435.35	0 205.00
12	1.80										
13	1.80										
14	1.80										
15	1.80										
16	1.80	6.1	7	2.89	43.38			34	510.41	0	2420
17	1.80			3.12	46.84		17	255.20	41	615.49	0 1203.00
18	1.80			3.77	56.60		18	270.22	41	615.49	0 2420.00
19	1.80										
20	1.80										
21	1.80										
22	1.80										
23	1.80	6.3	6.9	3.32	48.84			57	855.68	0	1046
24	1.80			3.54	53.14		16	240.19	60	900.72	0 1046.00
25	1.80			4.18	62.75			52	780.62	0	816
26	1.80										
27	1.70										
28	1.70										
29	1.70										
30	1.80			4.2	63.05		20	300.24	56	840.67	0 649.00
31											
AVG	1.92	6.20	6.98	2.54	39.65	14.38	224.87	36.85	576.10	0.00	811.85
MIN	1.70	6.10	6.90	1.00	16.96	7.00	140.11	14.00	280.22	0.00	70.00
MAX	2.40	6.30	7.00	4.20	63.05	20.00	300.24	60.00	900.72	0.00	2420.00

FAILED TO (BOD)
GET TWO
SAMPLES

TOOK
3 SAMPLES
1ST WEEK
OF JULY

Sanitary Sewer Overflow Monthly Report

Facility Name: Marion, City of Permit Number: AR0021971 Reporting Period (Month/Year): JUNE 2015
 No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact		CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building


Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location

Signature of Cognizant or Ranking Official: *[Handwritten Signature]*
 Date: 7/13/15

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

31 MIL
MARION

72364



ENFORCEMENT
DIVISION

ADEQ
5301 NORTHSORE DR.
NORTH LITTLE ROCK, AR.

72118-5317