

# ilities

for February 2017

nsas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
Quandt Ave & Crouch St. Springdale, AR 72764	100 gal	Grease	Jet/Vac	None	Overflow into storm drain.

ment and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and n my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.”



Date 03/10/2017