

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for MAY 2018

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
05/09/2018	1:30 pm-2:00pm	30 min.	301 Holcomb St. Springdale, AR 72764	10 gal	Debris	Jet-Vac	None	Overflow soaked into ground.
05/10/2018	11:30 am-12:30 pm	1 hr.	1711 Ford Ave. Springdale, AR 72764	25 gal	Debris	Jet-Vac- Pretreatment Coordinator will work with business owner to prevent prohibited discharge in the future.	None	Overflow into storm drain.

"[certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations,"

Signature  Date 06/12/2018