

Springdale Water Utilities


Springdale, Arkansas

System Overflow Report for May 2020

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

| Date | Time | Duration | Address | Est. Vol. | Cause of overflow | Remedial Action | Environmental Impact | Discharge Location |
|------------|-------------------|----------|--|-----------|-------------------|---|----------------------|--------------------|
| 05/18/2020 | 8:30 am – 9:00 am | 30 mins. | 4006 Holt Ave. Springdale, AR 72762 | 1000 gal | Vandalism | Jet/Vac, Spread Lime on Affected Area. Secured Manhole Keyhole Opening. | None | Into storm drain. |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature 

Date: 06/09/2020