

Springdale Water Utilities

Springdale, Arkansas


System Overflow Report for August 2022

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
08/23/2022	8:40 am	Still ongoing	1495 Wagnsworth Ave Springdale, AR 72762 200 ft North of manhole #6148	50 gal	Main line Overflow	Investigation ongoing	None	Into dry creek bed-soaking into ground.
08/27/2022	3:00 pm- 5:00 pm	2 hrs.	3919 N Oak Street Springdale, AR 72764	50 gal	Line failure/break	Spread Lime on affected area. Repair line	None	Into ditch-soaked into ground

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date: 09/16/2022