

Springdale Water Utilities

Springdale, Arkansas
System Overflow Report for October 2012



This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
10/04/2012	9:00 am – 9:30 am	30 min.	1913 Horseshoe Dr. Springdale, AR	25 gal	Roots	Jet-Vac/Hydro Cleaned	None	Manhole overflow onto grass surface, absorbed into ground.
10/06/2012	7:00 am – 11:00 am	4 hrs.	504 Buford St. Springdale, AR	500 gal	Roots/Grease	Jet-Vac/Hydro Cleaned	None	Overflow from manhole into storm drain.
10/11/2012	9:30 pm – 10:30 pm	1 hr.	800 Andy St. Springdale, AR	25 gal	Roots/Grease	Jet-Vac/Disinfected and Deodorized	None	Sewage overflow in residence basement, as a result of main line stoppage.
10/12/2012	2:30 pm – 2:24 pm	15 min.	171 Old Wire Rd. Springdale, AR	250 gal	Roots/Debris-paper towels	Jet-Vac/Disinfected and deodorized/Hydro Cleaned	None	Overflow from manhole went into grass ditch. Overflow from open cleanout in garage went into garage.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature *Larry Phillips* Date 11-16-12

Springdale Water Utilities
 Springdale, Arkansas
System Overflow Report for October 2012

POST
 NOV 16 2012
MARKED

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
10/29/2012	3:00 pm - 4:00 pm	1 hr.	2105 Oakhill Dr. Springdale, AR	50 gal	Roots	Jet-Vac/Hydro Cleaned	None	Overflow from manhole in street to storm drain.
10/30/2012	3:30 pm - 4:30 pm	1 hr.	5909 Wilkerson Dr. Johnson, AR	2500 gal	Grease	Jet-Vac/Hydro Cleaned/Spread Lime on Affected area.	None	Manhole overflow into dirt drainage ditch in wooded area.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature *Jerry Phillips* Date 11-16-12