

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for May 2022

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
05/04/2022	4:40 pm 4:54 pm	14 mins.	1027 Lowell Rd Springdale, AR 72764 Manhole # 6768	35 gal	Grease	Jet-Vac	None	Into ditch
05/05/2022	8:10 am 9:10 am	1 hr.	216 E. Velma Ave Springdale, AR 72764	100 gal	1 & 1 Rainfall	Cleaned area, further investigation	None	Into yard
05/05/2022	2:50 pm 3:30 pm	40 mins.	219 Ahlstrand Springdale, AR 72762 Manhole # 9028	50 gal	Debris	Jet-Vac, Removed mechanical plug after camera inspection	None	Into yard, soaked into ground
05/05/2022	8:50 am 9:40 am	50 mins.	3332 Kibbe Cove Springdale, AR 72764 Two Manholes- #4277 - #4278	5000 gal	Equipment failure	Cleaned affected area, Repaired controls equipment & starter	None	Into ditch

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature _____ Date: 06/8/2022



Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for May 2022

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
05/05/2022	9:00 am 5:30 pm	8 hrs., 30 mins.	603 Sanders Springdale, AR Manhole # 6386	20,000 gal	I & I rainfall	Cleaned up debris and applied lime on affected area	None	Into Spring Creek
05/05/2022	9:00 am 5:30 pm	8 hrs., 30 mins	1375 N Thompson Springdale, AR Manhole # 145	5,000 gal	I & I rainfall	Cleaned up debris and applied lime on affected area	None	Into field
05/05/2022	9:00 am 5:30 pm	8 hrs., 30 mins	N Shiloh Springdale, AR Manhole # 6388	5,000 gal	I & I rainfall	Cleaned up debris and applied lime on affected area	None	Into field

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature _____



Date: 06/08/2022