

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for June 2013

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
06/24/2013	5:00 pm – 5:30 pm	½ hr.	227 Gates Ave. Springdale, AR	50 gal	Roots/Grease	Jet-Vac/Spread lime on affected area.	None	Overflow went into yard and absorbed ground.

“I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.”

Signature


Heath G. Ward

Date

7-15-2013



Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769

CERTIFIED MAIL™



7012 3050 0000 5906 6606

NORTHWEST AR PADP
AR 727 2 L
17 JUL 2013 PM




USA
FIRST-CLASS
FOREVER

ADEQ
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118



1000



72118

U.S. POSTAGE
PAID
SPRINGDALE, AR
72764
JUL 17, '13
AMOUNT

\$6.11
00044614-03

7211835328

