

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for April 2013

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
04/18/2013	12:40 pm- 2:10 pm	1 ½ hr.	1308 Silent Grove Rd. Springdale, AR	200 gal	Roots	Jet-Vac/Spread Lime on Affected area.	None	Overflow was in alley behind residence, liquid was absorbed by ground, no solids, no runoff.
04/19/2013	10:30 am- 11:30 am	1 hr.	4008 Watkins Ave. Springdale, AR	200 gal	Grease	Jet-Vac/Hydro Cleaned	None	Manhole overflow ran into storm drain.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature

Nath A. Ward

Date

5-14-2013

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769


CERTIFIED MAIL™



7012 3050 0000 5906 6576



1000



72118


NORTHWEST AR P&DF

AR 72721

U.S. POSTAGE
PAID
SPRINGDALE, AR
72764
MAY 14, 13
AMOUNT

\$5.85
00031674-42

USA
CLASS



USPS

ADEQ
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317

72118\$5317

