

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for January 2013

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
01/02/2013	1:00 pm – 2:00 pm	1 hr.	2706 Eidson St. Springdale, AR	200 gal	Roots	Jet-Vac/Hydro Cleaned	None	Overflow ran into storm drain.
01/21/2013	7:00 pm – 9:00 pm	2 hr.	114 Sage Ave. Springdale, AR	3000 gal	Grease	Jet-Vac/Hydro Cleaned /Spread Lime on Affected Area	None	Overflow from manhole ran into dirt, grass covered ditch, and absorbed into ground.


"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature *Jerry Phillips*


Date 2-11-13

CERTIFIED MAIL™


Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769



7012 2210 0002 2221 6350



ADEQ
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118



U.S. POSTAGE
PAID
SPRINGDALE, AR
72764
FEB 13, '13
AMOUNT

1000

72118

\$5.85
00031674-42

72118*5317 R015

