

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for April 2015

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
04/27/2015	8:10 am-9:00 am	50 min.	1509 Wesley Ave Springdale, AR	100 gal	Debris	Jet-Vac, Disinfected and Deodorized	None	Floor Drain – Into building
04/27/2015	8:50 am-9:50 am	1 hr.	1003 Thomas Blvd Springdale, AR	200 gal	Roots, Grease	Jet-Vac	None	Clean-out-onto ground and into street.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature Keith C. Ward

Date May 12, 2015

OF THE RETURN ADDRESS, FOLD AT DOTTED LINE

CERTIFIED MAIL™

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769



7013 0600 0001 6399 9286

ADEQ
NPDES ENFORCEMENT SECTION
5301 NORTSHORE DRIVE
NORTH LITTLE ROCK, AR 72118

72118+5317

NORTHWEST AR P&DF

APR 27 2 T


15 MAY 2015 PM



1000



72118



FOREVER
USA

Purple Martin

U.S. POSTAGE
SPRINGDALE, AR
MAY 27 2015
AMOUNT
\$6.21
R2303S102787-42

