

Springdale Water Utilities

Springdale, Arkansas


System Overflow Report for April 2016

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
04/09/2016	9:15 am-10:45	1 hr. 30 min.	4006 Lankford Ave. Springdale, AR	3 gal	Main Line Overflow	Jet-Vac	None	Confined to bathroom.
04/21/2016	4:00 pm-4:45 pm	45 min.	Main Dr. & Bail St. Johnson, AR	100 gal	Roots	Jet-Vac	None	Soaked into ground.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature _____



Date 05/16/2016

CERTIFIED MAIL™


Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769




7013 0600 0001 6399 9514

STOR 2165881122

**Arkansas Dept. of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317**



1000



72118

U.S. POSTAGE
PAID
GREENLAND,
72737
MAY 16, 16
AMOUNT

\$6.2

R2305E126078