

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for August 2014

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
08/21/2014	9:00 pm- 9:30 pm	30 min.	1009 Fraker Street Springdale, AR 72764	50 gal	Roots	Jet-Vac	None	Manhole into storm drain.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature Heath A. Wood Date 9-12-2014

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769




7012 3050 0000 5906 6781



1000

72118

NORTHWEST AR POSTAGE
U.S. POSTAGE
AR 72769
SPRINGDALE, AR
SEP 15 2014 4:27 PM
AMOUNT
\$6.21
00018142-06



RETURN RECEIPT
REQUESTED

ADEQ
NPDES Enforcement Section
5301 Northshore Drive
Little Rock, AR 72118

72118X5328

