

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for February 2014

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
02/04/2014	5:30 pm-6:45 pm	1 hr. 15 mins.	510 Black Oak Ave. Springdale, AR	15 gal	Grease	Jet-Vac	None	10 gallons from cleanout into yard. Less than 5 gallons from drain onto floor of residence. cleaned by resident.
02/07/2014	2:00 pm-2:50 pm	50 mins.	171 Old Wire Rd. Springdale, AR	15 gal	Debris	Jet-Vac	None	Cleanout into building (garage). Overflow contained within garage.
02/15/2014	9:30 am-10:30 am	1 hr.	206 E. Maple Ave. Springdale, AR	700 gal	Grease	Jet-Vac, Hydro Cleaned, Spread Lime on Affected Area	None	Manhole into storm sewer.
02/15/2014 02/17/2014	7:00 pm-8:30 pm	49 ½ hrs.	111 San Jose Dr. Springdale, AR	500 gal	Grease	Jet-Vac, Spread Lime on Affected Area.	None	Overflow from manhole east of property went onto and soaked into ground.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature

Heath C. Ward

Date

March 13, 2014

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for February 2014

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
02/24/2014	10:00 am- 10:45 am	45 mins.	3511 Silent Grove Rd. Springdale, AR	200 gal	Air release valve failure.	Jet-Vac, Hydro Cleaned, Spread Lime on Affected Area.	None	Overflow from air release valve went onto and soaked into ground.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature Heath A. Wood

Date March 13, 2014

Springdale Water Utilities
P.O. Box 769
Springdale, AR 72118



CERTIFIED MAIL™



7013 1090 0002 0959 1999



UNITED STATES
POSTAL SERVICE



U.S. POSTAGE
PAID
GREENLAND, AR
72737
MAR 14, '14
AMOUNT

1000

72118

\$7.19

0315 2002

ADEQ
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118

