

Springdale Water Utilities

Springdale, Arkansas


System Overflow Report for February 2016

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
02/08/2016	10:00 pm- 11:00 pm	1 hr.	Intersection of Sycamore Place & Redwood St. Springdale, AR 72762	50 gal	Grease	Jet-Vac	None	Into storm drain.
02/21/2016	3:22 pm- 4:20 pm	58 min.	1603 Watson Ave. Springdale, AR 72762	300 gal	Grease	Jet-Vac, Hydro Cleaned	None	Into storm drain.
02/21/2016	4:20 pm- 5:30 pm	1 hr. 10 min.	2409 McRay Ave. Springdale, AR 72762	20 gal	Roots	Jet-Vac	None	Into storm drain.
02/27/2016	3:30 pm- 4:00 pm	30 min.	111 San Jose Dr. Springdale, AR 72764	200 gal	Grease	Machine Rodded, Jet-Vac, Hydro Cleaned, and Spread Lime on affected area.	None	Into ditch.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date 03/15/2016

CERTIFIED MAIL™

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769





7013 0600 0001 6399 9491

ADEQ
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317

NORTHWEST AIR FLOW

1000



72118

U.S. POSTAGE
PAID
GREENLAND, AR
72737
MAR 15 16
AMOUNT
\$6.47
R2305E126078-07

72118-5317

