

# Springdale Water Utilities

Springdale, Arkansas


## System Overflow Report for January 2014

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
01/15/2014	10:38 am – 11:03 am	25 min.	2910 Silent Grove Rd. Springdale, AR 72762	1250 gal	Equipment Failure	Fixed PLC Programming and Swept up	None	Overflow from Wastewater Treatment Plant splitter box into storm drain.
01/22/2014	1:00 pm – 1:45 pm	45 min.	2100 Highway E 265 Springdale, AR 72764	500 gal	Grease	Jet Vac/Hydro Cleaned	None	Overflow from manhole into ditch.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature \_\_\_\_\_



Date \_\_\_\_\_

Feb 13, 2014

Springdale Water Utilities  
P. O. Box 769  
Springdale, AR 72765-0769





7012 3050 0000 5906 6705


NORTHWEST AR POST  
AR 727 1 L  
14 FEB 2014 PM

USA  
FIRST-CLASS

FOREVER



ADEQ   
NPDES Enforcement Section  
5301 Northshore Drive  
North Little Rock, AR 72118



U.S. POSTAGE  
PAID  
GREENLAND, AR  
72737  
FEB 14, 14  
AMOUNT

1000

72118

\$6.21  
cancel

7211835317

