

# Springdale Water Utilities


Springdale, Arkansas

## System Overflow Report for July 2016

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
07/06/2016	12:00 pm – 12:30 pm	30 min.	389 Old Wire Rd. Springdale, AR	50 gal	Roots	Jet-Vac	None	Overflow went into ditch.
07/09/2016	10:00 am- 11:15 am	1 hr 15 min.	819 Mill Street Springdale, AR	500 gal	Roots	Jet-Vac, Hydro Cleaned	None	Overflow went into ditch.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature 

Date 08/16/2016

Springdale Water Utilities  
P. O. Box 769  
Springdale, AR 72765-0769




7013 0600 0001 6399 9538

ADEQ  
NPDES Enforcement Section  
5301 Northshore Drive  
North Little Rock, AR 72118-5317

NORTHWEST ARKANSAS  
17 AUG 2016

U.S. POSTAGE  
PAID  
GREENLAND, AR  
72737  
AUG 17 16  
AMOUNT  
**\$6.21**  
R2305E126078-03



72118



1000

721185317

